



## REPORT

# Pre-Renovation Designated Substances Review

*Maison de la Francophonie d'Ottawa (Former Grant School), 2720 Richmond Road, Ottawa, Ontario*

Submitted to:

**Mr. Scott Divell, Tech. OAAAS**

Project Manager

J.L. Richards & Associates Limited

864 Lade Ellen Place

Ottawa, Ontario

K1Z 5M2

Submitted by:

**Golder**

1931 Robertson Road Ottawa, Ontario, K2H 5B7 Canada

+1 613 592 9600

Project No.: 1791616 (JLR Project No. 27672-000.1)

April 18, 2018



## Distribution List

1 e-copy: J.L. Richards & Associates Limited (JLR)



## EXECUTIVE SUMMARY

*The Executive Summary highlights key points from the report only. For complete information and findings, as well as the limitations, the reader should examine the complete report.*

Golder Associates Ltd. (Golder) was retained by J.L. Richards & Associates Limited (JLR) to provide a Pre-Renovation Designated Substances Review (DSR) for the proposed Maison de la Francophonie d'Ottawa (MFO) building renovation of former Grant School, located at 2720 Richmond Road, in Ottawa, Ontario (the "Site").

The focus of the DSS was the eleven designated substances, as defined in Ontario Regulation 490/09; *Designated Substances (O. Reg. 490/09)* made under the Ontario *Occupational Health and Safety Act, R.S.O. 1990 Chapter O.1*, as amended (*OH&S Act*). Substances surveyed included acrylonitrile, arsenic, asbestos, benzene, coke oven emissions, ethylene oxide, isocyanates, lead, mercury, silica and vinyl chloride.

Based on the information provided by JLR, the existing former Grant School building structure will be renovated to accommodate the MFO. Prior to the Site reviews, Golder reviewed available designated substances records and drawings, which were referenced for the current DSR, including but not limited to, the following pre-renovation designated substances report, which is included in Appendix F, along with a number of subsequent limited sampling and laboratory reports that were provided to and reviewed by Golder as part of the scope of work (section 3.0):

- "Centre Multiservices Francophone de l'Ouest d'Ottawa, Designated Substances Survey, 2720 Richmond Road, Ottawa, Ontario", prepared by EHS Partnerships Ltd., dated April 2012 (EHS Project No.: 04-0068-12-001)

The DSR was conducted over several Site visits, which occurred between February 1 and 14, 2018. A thorough investigation of the Site, including intrusive assessment and sampling, was conducted to identify and document the potential presence, quantity, and condition of designated substances. This report must be provided to contractors prior to conducting renovation or demolition work at the Site.

### Asbestos-Containing Materials

Based on a review of previous reports, the current Site reviews and subsequent analytical results, the following materials were identified to be asbestos-containing materials (ACMs) and are currently present at the Site. Any repair, removal, or disturbance of these materials must be conducted in accordance with Ontario Regulation 278/05: Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations, as amended (O. Reg. 278/05) and applicable specification sections:

- Black tar present on walls in Electrical Room 005 (samples 1A to 1C) containing 25% Chrysotile asbestos (newly identified).
- Grog parging material present around chimney pipe in Mechanical Room 002 (samples 2A to 2C) containing 65% Chrysotile asbestos (newly identified).
- Exterior white caulking present around South West Exterior Stage Door (samples 8A to 8C) containing 4% Chrysotile asbestos (newly identified).
- Plaster materials throughout the East Stairwell (samples 9A to 9C, 10A to 10C and 11A to 11C) containing 1 to 4% Chrysotile asbestos (newly identified).



- Cementitious parging material present on select areas of walls within Mechanical Room 002 and Electrical Room 004 (samples 12A to 12C) in the basement containing 1% Chrysotile asbestos (newly identified).
- Plaster layer over concrete surface of Gymnasium ceiling containing 3% Chrysotile asbestos (newly identified).
- Plaster present within proposed Elevator lobby 210 location on exterior east side of building could not be accessed but is assumed to be asbestos-containing as all other plaster at the Site is asbestos-containing (newly identified).
- Bell and spigot joint packing materials present within wall cavities where existing air ducts are present and in the proposed Community Centre 140 could not be sampled but are assumed to be asbestos-containing.
- Pipe straight insulation present inside west air duct wall cavity running between D144C, 215 and 318A (samples PS-1-A – PS-1-C) and potentially other locations at the Site containing 90% Chrysotile asbestos (previously identified).
- Elbow parging present inside west air duct wall cavity running between D144C, 215 and 318A (samples PR-1-A – PR-1-C) and potentially other locations at the Site containing 65% Chrysotile asbestos (previously identified).
- Plaster present throughout Ground, Second and Third Floors (samples PL-1-A – PL-1-C) containing 2% Chrysotile asbestos (previously identified).

Please note, the identified ACMs may exist in other areas of the Site. All materials found to be in likeness to identified ACMs must be assumed to be ACMs unless otherwise confirmed by laboratory analyses. Any contractors bidding on asbestos abatement work at the Site must satisfy themselves of the quantities of ACMs based on Site walkthrough observations and measurements. Sample Location Plans (Figures 1 through 4) included in Appendix E show approximate locations and extents of identified ACMs and may not be fully representative of Site conditions and concealed materials. The bidding contractors must satisfy themselves of the locations and extents of ACMs to be removed.

### Lead-Containing Materials

Based on the analytical results, the lead concentrations in the following paints were found to be above the laboratory reporting detection limit (RDL), and therefore, considered to be lead-containing:

- White wall paint present on walls from the basement to the fourth floor (sample PS-2)
- Grey floor paint present within the basement and on the east and west stairs (sample LBP-G)
- Yellow paint present on brick in various areas from the basement to the third floor (sample LBP-J)

Lead may also be present in solder on pipe joints at the Site. In addition, if cable wrapping, ceramic glazes, batteries, lead sheeting, flashing or brick ties are discovered during renovation, repair, construction or demolition activities conducted at the Site, these materials should be treated as lead-containing until tested and proven otherwise.



## Mercury

The fluorescent light tubes/bulbs observed to be present throughout the attic space and potentially other locations at the Site are suspected to contain mercury vapour. If fluorescent light tubes and/or bulbs are to be removed during renovation, demolition or construction activities, they should remain unbroken and kept separate from all other waste to prevent damage prior to disposal. If mercury vapours are not present in fluorescent light tubes and bulbs, the Ontario Ministry of the Environment and Climate Change (MOECC) does not consider them a hazardous waste product. However, if it is not possible to confirm the absence or presence of mercury vapours, they must be treated as mercury waste. Mercury-containing thermostats were not observed within the designated project work areas at the Site.

## Silica-Containing Materials

Presumed silica-containing materials (SCMs) within the designated project work areas at the Site include plaster materials, concrete, brick, mortar and other masonry products, along with any other aggregates used to construct the Site which were observed to be in poor to good condition.

## Other Designated Substances

No other designated substances, as defined in *O. Reg. 490/09* under the *OH&S Act*, were observed within the project work areas of the Site. If any additional materials are identified and are expected to be impacted by the project that are not otherwise mentioned within this report, Golder should be contacted to provide further evaluation.



# Table of Contents

<b>EXECUTIVE SUMMARY .....</b>	<b>i</b>
<b>1.0 INTRODUCTION .....</b>	<b>1</b>
<b>2.0 PROJECT BACKGROUND .....</b>	<b>1</b>
<b>3.0 SCOPE OF WORK.....</b>	<b>1</b>
<b>4.0 REGULATIONS, GUIDELINES AND STANDARDS.....</b>	<b>2</b>
<b>5.0 METHODOLOGY .....</b>	<b>2</b>
<b>6.0 RESULTS AND DISCUSSION .....</b>	<b>3</b>
6.1 Asbestos-Containing Materials .....	3
6.2 Lead-Containing Materials .....	4
6.3 Mercury-Containing Materials .....	5
6.4 Silica-Containing Materials.....	5
6.5 Other Designated Substances .....	5
<b>7.0 RECOMMENDATIONS .....</b>	<b>6</b>
7.1 Asbestos-Containing Materials .....	6
7.2 Lead-Containing Materials .....	6
7.3 Mercury-Containing Materials .....	7
7.4 Silica-Containing Materials.....	7
<b>8.0 LIMITATIONS.....</b>	<b>8</b>

## APPENDICES

### APPENDIX A

Regulations and Guidelines

### APPENDIX B

Methodology

### APPENDIX C

Spreadsheet of Findings

### APPENDIX D

Laboratory Test Reports

### APPENDIX E

Figures

### APPENDIX F

Reference Reports



## 1.0 INTRODUCTION

Golder Associates Ltd. (Golder) was retained by J.L. Richards & Associates Limited (JLR) to provide a Pre-Renovation Designated Substances Review (DSR) for the proposed Maison de la Francophonie d'Ottawa (MFO) building renovation of former Grant School, located at 2720 Richmond Road, in Ottawa, Ontario (the "Site").

Under Section 30 of the Ontario *Occupational Health and Safety Act*, Revised Statutes of Ontario 1990, as amended (the *OH&S Act*), before beginning a project, the owner shall determine whether any designated substances are present at the project site and shall prepare a list of all designated substances that are present at the site. The DSR was requested to fulfill this requirement.

The focus of the DSR was the eleven designated substances, as defined in Ontario Regulation 490/09 *Designated Substances* (*O. Reg. 490/09*) made under the *OH&S Act*. Substances surveyed included acrylonitrile, arsenic, asbestos, benzene, coke oven emissions, ethylene oxide, isocyanates, lead, mercury, silica and vinyl chloride.

## 2.0 PROJECT BACKGROUND

Based on the information provided by JLR, the existing former Grant School building structure will be renovated to accommodate the MFO. Prior to the Site reviews, Golder reviewed available designated substances records and drawings, which were referenced for the current DSR, including but not limited to, the following pre-renovation designated substances report, which is included in Appendix F, along with a number of subsequent limited sampling and laboratory reports that were provided to and reviewed by Golder as part of the scope of work (section 3.0):

- "Centre Multiservices Francophone de l'Ouest d'Ottawa, Designated Substances Survey, 2720 Richmond Road, Ottawa, Ontario", prepared by EHS Partnerships Ltd., dated April 2012 (EHS Project No.: 04-0068-12-001)

## 3.0 SCOPE OF WORK

Golder's scope of work was limited to the following, as based on communications with JLR:

- Reviewing the historic designated substances reports for the Site included in Appendix F.
- Visually identifying and inventorying previously identified and suspected designated substances not previously identified in the historic reports including but not limited to:
  - Non-friable and friable asbestos-containing materials (ACMs)
  - Lead-containing materials (LCMs), including lead-based paints (LBPs)
  - Mercury-containing materials and equipment
  - Silica-containing materials
- Collecting limited quantities of representative bulk samples of suspected ACMs and suspected LBPs and submitting these samples to an independent accredited laboratory for analysis.
- Preparing an electronic (PDF) copy of a pre-renovation DSR report that incorporates the findings and analytical results of previous reports on remaining designated substances at the Site. The DSR report provides approximate locations, conditions and quantifications of designated substances at the Site.



- Preparing specification sections and associated figures. Figures 1 through 4, which are provided as attachments to the DSR report, delineate the sample locations and the extent of the remaining ACMs at the Site. The following specification sections developed for the removal/disturbance of designated substances are provided under separate cover.
  - Section 02 82 00.01 Type 1 Asbestos Operations – Minimum Precautions
  - Section 02 82 00.02 Type 2 Asbestos Operations – Intermediate Precautions
  - Section 02 82 00.03 Type 3 Asbestos Operations – Maximum Precautions
  - Section 02 82 17.01 Type 1 Silica Operations – Minimum Precautions
  - Section 02 82 17.02 Type 2 Silica Operations – Intermediate Precautions
  - Section 02 83 10 Type 1 Lead Operations – Minimum Precautions
  - Section 02 83 11 Type 2 Lead Operations – Intermediate Precautions
  - Section 02 86 01 Mercury Precautions

All work was performed by an appropriately qualified and experienced EHS technician under the direction of a Canadian Registered Safety Professional (CRSP) and reviewed by a Certified Industrial Hygienist (CIH), as required.

## 4.0 REGULATIONS, GUIDELINES AND STANDARDS

Section 30 of the *OH&S Act* requires that, prior to beginning a construction project (including building renovation or demolition); a document summarizing the presence of designated substances must be available to contractors and subcontractors. This report serves that purpose.

A summary of applicable regulations, guidelines and standards are included in Appendix A.

## 5.0 METHODOLOGY

The Site assessment was completed between February 1 and 14, 2018 by the Golder Ottawa's Environmental Health and Safety (EHS) team, including: Tim Seabert, Project Manager; Kyle Heagle, EHS Technician; and Paul Park, EHS Technician.

Various reports related to the assessment and remediation of designated substances at the Site have been provided by JLR and reviewed by Golder as part of the DSR. Golder conducted a data gap analysis, confirmed previous findings and conducted additional sampling of suspect materials not previously sampled, as required. Golder reports only on the remaining designated substances at the Site, as based on the findings of the current DSR.

Site work was conducted in accordance with standards outlined in the *OH&S Act* and Golder's Site-specific Health and Safety Plan without incident.

A summary of applicable methodologies is included in Appendix B.



## 6.0 RESULTS AND DISCUSSION

### 6.1 Asbestos-Containing Materials

A total of 53 samples of suspected ACMs, not previously sampled, were collected at the Site by Golder and submitted for asbestos content analysis representing 18 homogeneous materials, including:

- Black tar on walls (samples 1A to 1C)
- Caulking and parging materials around chimney (samples 2A to 2C);
- Cementitious infill around chimney (samples 3A to 3C);
- Black tar paper between terracotta blocks and bricks (samples 4A to 4C);
- Fibreboard materials (samples 5A to 5C and 6A to 6C);
- Exterior brick mortar (samples 7A to 7C);
- Exterior caulking materials (samples 8A to 8C);
- Stairwell plaster materials, skim and base coats (samples 9A to 9C, 10A to 10C and 11A to 11C);
- Cementitious parging material (samples 12A to 12C);
- Plaster on ceiling (samples 13A to 13C); and,
- Black tar on exterior building surfaces (samples 14A to 14C).

Based on a review of previous reports, the current Site reviews and subsequent analytical results, the following materials were identified to be ACMs and are currently present at the Site. Any repair, removal, or disturbance of these materials must be conducted in accordance with Ontario Regulation 278/05: *Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations*, as amended (O. Reg. 278/05) and applicable specification sections:

- Black tar present on walls in Electrical Room 005 (samples 1A to 1C) containing 25% Chrysotile asbestos (newly identified)
- Greg parging material present around chimney pipe in Mechanical Room 002 (samples 2A to 2C) containing 65% Chrysotile asbestos (newly identified)
- Exterior white caulking present around South West Exterior Stage Door (samples 8A to 8C) containing 4% Chrysotile asbestos (newly identified)
- Plaster materials throughout the East Stairwell (samples 9A to 9C, 10A to 10C and 11A to 11C) containing 1 to 4% Chrysotile asbestos (newly identified)
- Cementitious parging material present on select areas of walls within Mechanical Room 002 and Electrical Room 004 (samples 12A to 12C) in the basement containing 1% Chrysotile asbestos (newly identified)
- Plaster layer over concrete surface of Gymnasium ceiling containing 3% Chrysotile asbestos (newly identified)
- Plaster present within proposed Elevator lobby 210 location on exterior east side of building could not be accessed but is assumed to be asbestos-containing as all other plaster at the Site is asbestos-containing (newly identified)



- Bell and spigot joint packing materials present within wall cavities where existing air ducts are present and in the proposed Community Centre 140 could not be sampled but are assumed to be asbestos-containing
- Pipe straight insulation present inside west air duct wall cavity running between D144C, 215 and 318A (samples PS-1-A – PS-1-C) and potentially other locations at the Site containing 90% Chrysotile asbestos (previously identified)
- Elbow parging present inside west air duct wall cavity running between D144C, 215 and 318A (samples PR-1-A – PR-1-C) and potentially other locations at the Site containing 65% Chrysotile asbestos (previously identified)
- Plaster present throughout Ground, Second and Third Floors (samples PL-1-A – PL-1-C) containing 2% Chrysotile asbestos (previously identified)

Analytical laboratory results of all suspected ACM samples collected at the Site by Golder are summarized within Appendix C (Table C.1) and the Laboratory Test Report on the asbestos analysis are included within Appendix D. The sample locations and extent of the remaining ACMs at the Site are illustrated on the Site figures (figures 1 through 4) included in Appendix E. For previous reports on samples and analytical results of suspected ACMs tested at the Site and not listed here, see Appendix F.

Please note, the identified ACMs may exist in other areas of the Site. All materials found to be in likeness to identified ACMs must be assumed to be ACMs unless otherwise confirmed by laboratory analyses. Any contractors bidding on asbestos abatement work at the Site must satisfy themselves of the quantities of ACMs based on Site walkthrough observations and measurements. Sample Location Plans (Figures 1 through 4) included in Appendix E show approximate locations and extents of identified ACMs and may not be fully representative of Site conditions and concealed materials. The bidding contractors must satisfy themselves of the locations and extents of ACMs to be removed.

## 6.2 Lead-Containing Materials

Based on the analytical results, the lead concentrations in the following paints were found to be above the laboratory reporting detection limit (RDL), and therefore, considered to be lead-containing:

- White wall paint present on walls from the basement to the fourth floor (sample PS-2)
- Grey floor paint present within the basement and on the east and west stairs (sample LBP-G)
- Yellow paint present on brick in various areas from the basement to the third floor (sample LBP-J)

The analytical laboratory results of the suspect LCP samples are summarized within Appendix C (Table C.2) and the Laboratory Test Report on the lead analysis is included within Appendix D. The sample locations are illustrated in the Site Plan found in Appendix E. For previous reports on samples and analytical results of suspected LCPs tested at the Site and not listed here, see Appendix F.

Lead may also be present in solder on pipe joints at the Site. In addition, if cable wrapping, ceramic glazes, batteries, lead sheeting, flashing or brick ties are discovered during renovation, repair, construction or demolition activities conducted at the Site, these materials should be treated as lead-containing until tested and proven otherwise.



### 6.3 Mercury-Containing Materials

The fluorescent light tubes/bulbs observed to be present throughout the attic space and potentially other locations at the Site are suspected to contain mercury vapour. If fluorescent light tubes and/or bulbs are to be removed during renovation, demolition or construction activities, they should remain unbroken and kept separate from all other waste to prevent damage prior to disposal. If mercury vapours are not present in fluorescent light tubes and bulbs, the Ontario Ministry of the Environment and Climate Change (MOECC) does not consider them a hazardous waste product. However, if it is not possible to confirm the absence or presence of mercury vapours, they must be treated as mercury waste. Mercury-containing thermostats were not observed within the designated project work areas at the Site.

Disposal of materials containing mercury shall be performed in accordance with Ontario Regulation 347; *General – Waste Management* made under the Ontario Environmental Protection Act, R.S.O. 1990, as amended (*O. Reg. 347*).

### 6.4 Silica-Containing Materials

Presumed silica-containing materials (SCMs) within the designated project work areas at the Site include plaster materials, concrete, brick, mortar and other masonry products, along with any other aggregates used to construct the Site which were observed to be in poor to good condition.

Disturbance to the SCMs during this project may cause worker exposure to be greater than the Ontario Exposure Limit Time-Weighted Average (OEL-TWA). Disturbance of these materials should be conducted in accordance with *O. Reg. 490/09* under the *OH&S Act* and the MOL silica guideline; *Silica on Construction Projects* updated in April 2011 (MOL Silica Guideline).

### 6.5 Other Designated Substances

No other designated substances, as defined in *O. Reg. 490/09* under the *OH&S Act*, were observed within the project work areas of the Site. If any additional materials are identified and are expected to be impacted by the project that are not otherwise mentioned within this report, Golder should be contacted to provide further evaluation.



## 7.0 RECOMMENDATIONS

This report was prepared to fulfil the duty of the project owner's requirement under Section 30(1) of the *OH&S Act*, and the requirements of Section 10 of *O. Reg. 278/05*. This report must be provided to contractors prior to conducting demolition or renovation work at the Site.

Based on the information provided by JLR, it is understood that there will be partial removal of identified designated substances at the Site and the bidding contractors will be responsible to coordinate the project specification sections and drawings with the DSR report to account for any impacts to designated substances at the Site. Any disturbance to the designated substances within the project area(s) of the Site must be carried out in accordance with applicable regulations and the following project specification sections:

### **Asbestos-Containing Materials**

- 02 82 00.01 Type 1 Asbestos Abatement – Minimum Precautions
- 02 82 00.02 Type 2 Asbestos Abatement – Intermediate Precautions
- 02 82 00.03 Type 3 Asbestos Abatement – Maximum Precautions

### **Lead-Containing Materials**

- 02 83 10 Type 1 Lead Operations – Minimum Precautions
- 02 83 11 Type 2 Lead Operations – Intermediate Precautions

### **Mercury-Containing Materials**

- 02 86 01 Mercury Precautions

### **Silica-Containing Materials**

- 02 82 17.01 Type 1 Silica Operations – Minimum Precautions
- 02 82 17.02 Type 2 Silica Operations – Intermediate Precautions

## 7.1 Asbestos-Containing Materials

ACMs must be disturbed and/or removed in accordance with *O. Reg. 278/05*, made under the *OH&S Act*, and the applicable project specification sections prior to any disturbance caused by the repair, renovation or demolition operations. ACMs must be removed and disposed of in accordance with *O. Reg. 278/05*, *O. Reg. 347* and the project specification sections pertaining to ACMs listed in Section 7.0.

## 7.2 Lead-Containing Materials

Based on the findings of the DSR, the following recommendations are made with respect to suspect LCMs at the Site:

- 1) If materials that may contain lead are identified during renovation and/or demolition activities (e.g., solder on pipe joints, cable wrapping, ceramic glazes, or batteries), they must be treated as lead-containing until tested and proven otherwise.
- 2) Should LCMs be removed from the Site, they are to be recycled or disposed of at an approved landfill. If LCMs are to be disposed of in a landfill, waste characterization should be performed including, in the case of LCPs, analysis of both the painted surface and the underlying substrate for lead leachate, using the Toxicity Characteristic Leaching Procedure (TCLP) as specified in *O. Reg. 347*. Based on the results of the TCLP



analysis, removed LCMs would either be considered as construction waste or leachate toxic waste. All leachate toxic materials would require segregation and final disposal in a landfill licensed to accept leachate toxic waste by the MOECC.

- 3) Demolition, including any disturbance, of LCMs must be conducted in accordance with the OH&S Act, applicable regulations, the MOL lead guideline; Lead on Construction Projects updated in April 2011 (MOL Lead Guideline) and project specification sections pertaining to LCMs listed in Section 7.0.

### 7.3 Mercury-Containing Materials

The fluorescent light tubes/bulbs observed to be present throughout the attic space and potentially other locations at the Site are suspected to contain mercury vapour. Mercury-containing thermostats were not observed within the designated project work areas at the Site. Disposal of materials containing mercury shall be performed in accordance with *O. Reg. 347*.

Any removal and/or disturbance to the mercury-containing materials within the project area(s) of the Site must be carried out in accordance with applicable regulations and guidelines and the project specification sections pertaining to mercury-containing materials listed in Section 7.0.

### 7.4 Silica-Containing Materials

*O. Reg. 490/09*, Section 19, specifies that an employer shall carry out an assessment of the exposure or likelihood of exposure of a worker to a designated substance in the workplace and record it in writing. Based on the condition of SCMs at the time of the assessment and current use of the Site, the likelihood of worker exposure greater than the OEL-TWA is very minimal and no further worker exposure assessment is recommended at this time.

If conditions change or activities are scheduled where exposure to silica becomes more likely, an additional worker exposure assessment must be completed at that time. Precautions against silica exposure are only required for building materials in poor condition or during disturbance of these materials including, but not limited to, renovation or demolition activities. Demolition, including any disturbance, of these materials must be conducted in accordance with the OH&S Act, applicable regulations, the MOL Silica Guideline and project specification sections pertaining to SCMs listed in Section 7.0.



## 8.0 LIMITATIONS

This report was prepared for the exclusive use of the MFO and JLR. This report is based on samples and information collected during the Site visits conducted by Golder Associates Ltd., between February 1 and 14, 2018, and is based solely on Site conditions encountered at the time of the Site visits, as described in this report.

The conclusions and recommendations contained in this report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations.

The data and findings presented in this report are valid as of the date of the investigation. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.

The findings, observations and conclusions expressed by Golder Associates Ltd. in this report are not, and should not be considered, an opinion concerning compliance of any past or present owner or operator of the building with any federal, provincial or local laws or regulations.

Although efforts were made to expose and identify all potential designated substances within the specified areas at the Site, there is a possibility that additional designated substances may be present in concealed areas or other areas not included as part of this DSR. The DSR required destructive sampling to be performed and all samples were collected with the approval of the Site Representative.

As such, if additional and suspected designated substances are encountered during renovation and/or demolition activities that are not included in this report, it is recommended that a further investigation be conducted at that time. As such, in the case that suspected ACMs or LCMs cannot be tested, they must be treated as ACMs or LCMs, respectively, until proven otherwise. Should building materials encountered during any renovation and/or demolition activities be found to contain asbestos, these materials must be managed in accordance with O. Reg. 278/05.



## Signature Page

We trust that this report meets your requirements and current needs. If you have any questions regarding the content of this technical memorandum or require any further information, please do not hesitate to contact the undersigned at (613) 592-9600. Thank you for the opportunity to be of service. We look forward to working with you again

Sincerely,

**GOLDER ASSOCIATES LTD.**



Greg Slack, M.Sc., ROH, CIH  
*Industrial Hygienist*



Tim Seabert, M.Sc., CRSP  
*EHS Practice Leader / Occupational Hygienist*

TAS/GJS/ca

[https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/rpt01\\_1791616\\_mfo\\_grant\\_school\\_pre-reno\\_dsr\\_april2018.docx](https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/rpt01_1791616_mfo_grant_school_pre-reno_dsr_april2018.docx)

Golder and the G logo are trademarks of Golder Associates Corporation



**APPENDIX A**

# Regulations and Guidelines



## REGULATIONS AND GUIDELINES

### OH&S Act, R.S.O. 1990, c.0.1

The Ontario *Occupational Health and Safety Act* (OH&S Act), outlines designated substances that may be present at the Site. The designated substances referred to under Section 30 of the OH&S Act are regulated under two regulations, which specify occupational exposure limits and any required assessment and control programs. Section 30 of the OH&S Act requires that, prior to beginning a construction project (including site renovation or demolition) a document summarizing the presence of these designated substances must be available to contractors and subcontractors requesting tenders. This report serves that purpose, however; it does not exclude the requirement for project specifications and scaled drawings outlining abatement areas, quantities and specific procedures typically required in a demolition tender contract.

### Asbestos

Ontario Regulation 278/05 entitled *Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations*, as amended (O. Reg. 278/05), made under the OH&S Act, outlines specific procedures for the identification of ACMs in buildings and on construction sites and protocols for their removal. Under this regulation, if ACMs are suspected to be present or ought reasonably to be suspected, locations of the materials must be documented and re-inspected at reasonable intervals to determine their condition.

Prior to a re-development, renovation or demolition project, a document summarizing the presence of all ACMs must be available to contractors and subcontractors requested to tender. ACMs in good condition can remain at the Site in accordance with the details outlined for ongoing asbestos management. All ACMs must be removed or managed appropriately prior to any disturbance caused by the re-development, renovation or demolition process in accordance with provincial regulations.

R.R.O. 1990, Regulation 347 entitled *General – Waste Management* as amended (O. Reg. 347), made under the Ontario *Environmental Protection Act*, R.S.O. 1990, Chapter E.19, as amended sets out requirements for general waste management including ACM. The regulation defines "asbestos waste" as "solid or liquid waste that results from the removal of asbestos-containing construction or insulation materials or from the manufacture of asbestos-containing products and contains asbestos in more than a trivial amount or proportion". This regulation requires the disposal of asbestos waste in a double sealed container, properly labelled and free of cuts, tears or punctures. The waste must be disposed of in a licensed waste facility which has been properly notified of the presence of asbestos waste.

### Lead

Lead is regulated under Ontario Regulation 490/09 entitled *Designated Substances* (O. Reg. 490/09), as amended and made under the OH&S Act. This regulation prescribes occupational exposure limits (OELs) and other requirements surrounding engineering controls, work practices, hygiene practices and facilities for workers who may become exposed to lead.

The Occupational Health and Safety Branch of the Ontario Ministry of Labour (MOL) published their Guideline entitled *Lead on Construction Projects*, ("MOL Lead Guideline", revised April 2011) to raise the awareness of employers and workers in the construction industry of the hazards posed by lead in construction and the measures and procedures that should be taken to control those hazards. Currently, this document represents due diligence practice for lead exposure control on construction projects, as enforced by the MOL under the general duty clause 25(2)(h) of the OH&S Act. As such, it is referenced within the report, where appropriate, to provide guidance on appropriate handling and exposure control procedures when dealing with lead.



Golder understands the MOL currently does not include criteria for classification LCP, and that, as such, the MOL considers the presence of any detectable concentration of lead in a paint or coating as a LCP. Therefore, in these circumstances, Golder considers all paints with any detectable concentration of lead to be a LCP.

Disposal of lead must be conducted in accordance with the requirements of *O. Reg. 347*.

## **Mercury**

Mercury is regulated under *O. Reg. 490/09*. This regulation sets out occupational exposure standards and prescriptive requirements surrounding engineering controls, work practices and hygiene practices and facilities for workers who may become exposed to mercury.

Disposal of materials containing mercury shall be done in accordance with *O. Reg. 347*.

## **Silica**

Silica is regulated under *O. Reg. 490/09*. This Regulation sets out occupational exposure standards and prescriptive requirements surrounding engineering controls, work practices and hygiene practices and facilities for workers who may become exposed to crystalline silica, namely cristobalite, quartz and tripoli. As set out in *O. Reg. 490/09*, an employer shall take all reasonable precautions to prevent worker exposure to silica.

Procedures for workers involved in construction/demolition activities occurring on a site where silica is disturbed are outlined in the MOL Guideline entitled *Silica on Construction Projects*, ("MOL Silica Guideline", revised April 2011).

The MOL Silica Guideline is referenced within the report, where appropriate, to provide guidance on recommended handling and exposure control procedures when dealing with silica on construction projects. The MOL Silica Guideline is enforceable as a reasonable precaution under the general duty clause 25(2)(h) of the *OH&S Act*.

## **Other Designated Substances**

In addition to the four designated substances that have a high probability of being present at the Building, which are discussed in detail in the previous sections, the following seven designated substances as defined in the regulations under the *OH&S Act* were included in this survey: acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates and vinyl chloride. Based on Golder's professional experience, none of these substances were expected to be present and, as such, no specific observations or sampling of materials potentially containing these substances were undertaken.

<https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/appendix a - regulations and guidelines.docx>



**APPENDIX B**

# Methodology



## METHODOLOGY

### Suspect Asbestos-Containing Materials

Effective November 1, 2005, *O. Reg. 278/05*, stipulates that a minimum number of samples per “homogeneous material” (a material that is uniform in colour and texture) are required to verify the presence or absence of asbestos.

The number of samples of each “homogeneous material” was collected in accordance with Bulk Material Samples of *O. Reg. 278/05* summarized in Table B.1 below.

**Table 1: B.1: Bulk Samples - Asbestos**

Type of Materials	Size of Area of Homogeneous Materials	Minimum Number of Samples
Surfacing material, including without limitation material that is applied to surfaces by spraying, by troweling or otherwise. Examples include acoustical plaster on ceilings and fireproofing materials on structural members	Less than 90 m <sup>2</sup> (969 ft <sup>2</sup> )	3
	90 or more m <sup>2</sup> , but less than 450 m <sup>2</sup> (4,844 ft <sup>2</sup> )	5
	450 or more m <sup>2</sup> (more than 4,844 ft <sup>2</sup> )	7
Thermal insulation, except as described below	Any size	3
Thermal insulation patch	Less than 2 linear meters (6.6 ft.) or 0.5 m <sup>2</sup> (approximately 5.4 ft <sup>2</sup> )	1
Other material	Any size	3

Representative samples of suspected ACMs were submitted to an independent accredited laboratory (EMSL Canada, Inc., 22 Antares Drive, Ottawa, Ontario, NVLAP accreditation #201040-0) for asbestos content analysis. Polarized Light Microscopy was completed in accordance with EPA methodologies and dispersion staining techniques (EPA 600/R-93/116). Sample collection and analysis was conducted as per *O. Reg. 278/05*. Samples from homogeneous areas were grouped together and analyzed.

Materials reported to contain less than 0.5% asbestos (dry weight), including those referred to as less than the limit of detection (<LOD) or trace, are not considered to be asbestos-containing under *O. Reg. 278/05*. The LOD is 0.5%.

### Suspect Lead-Containing Materials

Analyzing, sampling, and visual assessment of suspected lead-containing materials, specifically paint, was completed as part of the survey. Samples of suspected lead-containing paints were extracted using a clean knife and scraping off a small piece of the material. Care was taken to penetrate all paint layers at each sample location.

Collected samples were placed in sealed bags and labelled for submission to EMSL Canada, Inc., 2756 Slough Street, Mississauga, Ontario (American Association for Laboratory Accreditation, Accredited Environmental Testing Certificate #2845.08) for lead analysis following EPA method SW 846 3050B/7000B. Each sample is digested, diluted and analyzed by flame atomic absorption spectroscopy.



## **Suspected Mercury-Containing Materials**

An assessment for potential mercury-containing equipment installed at the Site was completed as part of the survey. Mercury-containing thermostats and fluorescent light tubes and bulbs that may be impacted during the project activities were noted, where observed. Elemental mercury may be present in switches and electrical switch gear at the Site. Trace amounts of mercury are present as a vapour within metal halide light bulbs and fluorescent light tubes and bulbs. These light bulbs and tubes may pose an occupational hazard to unprotected workers if broken.

## **Suspected Silica-Containing Materials**

A visual assessment was completed to determine the potential for silica-containing materials to be present within the project areas at the Site.

## **Other Designated Substances**

Other designated substances as defined in *O. Reg. 490/09* under the *OH&S Act* include acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates and vinyl chloride. Based on professional experience, none of these substances were expected to be present and, as such, no specific observations or sampling of materials potentially containing these substances were undertaken as part of this assessment.

[https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/appendix b - methodology.docx](https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/appendix%20b%20-%20methodology.docx)




**APPENDIX C**

# Spreadsheet of Findings



Table C.1: Summary of Materials Sampled for Asbestos Analysis

Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Black Tar	Present on walls within Electrical Room 005	56 m <sup>2</sup>	Good	No	A	1A – 1C	25% Chrysotile	
Red Caulking	Present around the chimney pipe inside Mechanical Room 002	1.5 linear meters	N/A	N/A	N/A	2 Caulk A – 2 Caulk C	N/A	
Grey Parging	Present on top of Red Caulking around chimney pipe inside Mechanical Room 002	1.5 linear meters	Poor	Yes	C	2 Parging A – 2 Parging C	65% Chrysotile	



Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Concrete Infill	Present around chimney pipe inside Mechanical Room 002	N/A	N/A	N/A	N/A	3A – 3C	N/A	
Black Tar Paper	Present between terracotta and red clay brick	N/A	N/A	N/A	N/A	4A – 4C	N/A	
Fiberboard (Bulletin Boards)	Present in classrooms and corridors	N/A	N/A	N/A	N/A	5A – 5C	N/A	



Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Fiberboard (Behind Plaster)	Present behind plaster in West Entrance and South Entrance to Gymnasium	N/A	N/A	N/A	N/A	6A – 6C	N/A	
Exterior Brick Mortar	Present on the exterior of the Stage Area of the Gymnasium	N/A	N/A	N/A	N/A	7A – 7C	N/A	
Exterior White Caulking	Present around South West Exterior Stage Door	12 Linear Meters	Poor to Fair	No	A	8A – 8C	4% Chrysotile	






Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Plaster	East stairwell – First floor to first landing	90 m <sup>2</sup>	Fair to Good	Yes	A	9A – 9C	Skim Coat: 2% to 4% Chrysotile  Base Coat: None detected	
Plaster	East stairwell – First landing to second floor	50 m <sup>2</sup>	Fair to Good	Yes	A	10A – 10C	Skim Coat: 4% Chrysotile  Base Coat: None detected	
Plaster	East stairwell – second floor to third floor	120 m <sup>2</sup>	Fair to Good	Yes	A	11A – 11C	Skim Coat: 2% Chrysotile  Base Coat: 1% Chrysotile	





Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Cementitious Parging	Present on select areas of walls within Mech 002, and Elec 004 in the basement	6 m <sup>2</sup>	Fair to Good	Yes	A	12A – 12C	1% Chrysotile	
Thin plaster layer over concrete surface of gymnasium ceiling	Present in gymnasium	85 m <sup>2</sup>	Fair to Good	Yes	C	13A – 13C	3% Chrysotile	
Tar Paper	Present along the exterior east side of the foundation	N/A	N/A	N/A	N/A	14A – 14C	None detected	



Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Plaster	Present within proposed Elevator lobby 210 location on exterior east side of building	28 m <sup>2</sup>	Poor	Yes	B	No sample collected as material could not be safely accessed	Assumed to be asbestos-containing as all other plaster at the Site is asbestos-containing	
Bell and spigot joint packing materials	Present within wall cavities where existing air ducts are present and in the proposed Community Centre 140	Unknown	Good	Yes	D	No sample collected as sampling would have impacted the integrity of the piping system	Assumed as bell and spigot joints are known to contain ACMs	
Pipe Straight Insulation	Present inside west air duct wall cavity running between D144C, 215 and 318A	Unknown	Fair to Poor	Yes	D	Historical EHSP Report: 04-0068-12-001  PS-1-A – PS-1-C	90% Chrysotile	



Material Description	Material Location <sup>(1)</sup>	Observed Estimated Quantity	Condition	Friable (Yes / No)	Accessibility <sup>(3)</sup>	Sample Number	Asbestos Concentration (%) and Type	Photograph
Elbow Parging	Present inside west air duct wall cavity running between D144C, 215 and 318A	Unknown	Fair to Poor	Yes	D	Historical EHSP Report: 04-0068-12-001 PR-1-A – PR-1-C	65% Chrysotile	
Plaster	Present throughout Ground, Second and Third Floors	2,900 m <sup>2</sup>	Fair to Poor	Yes	A	Historical EHSP Report: 04-0068-12-001 PL-1-A – PL-1-C	2% Chrysotile	

Notes: (1) The confirmed asbestos-containing materials (ACMs) were observed throughout the Site. All materials found to be in likeness to identified ACMs should be assumed to be ACMs unless otherwise confirmed by laboratory analyses.

(2) "N/A" indicates not applicable. Sampled material contains less than 0.5% of asbestos by weight and is not considered to be an ACM in accordance with O. Reg. 278/05.

(3) The accessibility of known ACMs is rated in accordance with the following criteria:

**Access (A):** Areas of the building within reach (from floor level) of all building users. Includes areas such as gymnasiums, workshops, and storage areas where activities of the building users (for example basketball on gym ceiling) may result in disturbance of ACM not normally within reach from floor level.

**Access (B):** Frequently entered maintenance areas within reach of maintenance staff, without the need for a ladder. Includes: frequently entered pipe chases, tunnels and service areas or areas within reach from a fixed ladder or catwalk, for example tops of equipment, mezzanines.



**Access (C) Exposed:** Areas of the building above 6'0" where use of a ladder is required to reach the ACM. Only refers to asbestos-containing material materials that are exposed to view, from the floor or ladder, without removing or opening other building components such as ceiling tiles, or service access doors or hatches. Does not include infrequently-accessed service areas of the building.

**Access (D) Concealed:** Areas of the building which require the removal of a building component, including lay-in ceilings and access panels into solid ceiling systems such as a ventilation plenum. Includes rarely-entered crawl spaces, attic spaces, etc. Observations are limited to the extent visible from the access points.



**Access (E) Concealed:** Areas of the building behind inaccessible solid ceiling systems, walls, or mechanical equipment, etc., where demolition of the ceiling, wall or equipment, etc., is required to reach the ACM. Evaluation of condition and extent of ACM is limited or impossible, depending on the assessor's ability to visually examine the materials in areas rated Access (D).




Table C.2: Summary of Paints Sampled for Lead Analysis

Description / Location of Material	Condition	Lead Concentration (ppm)	Sample Number	Lead-Containing (Yes/No)	Photograph
Blue paint – Present on floors throughout second floor and third floor	N/A <sup>(1)</sup>	<88	Lp-01	No	
Lead solder / Present bell and spigot joints inside wall cavities for air ducts	Good	No sample collected as sampling would have impacted the integrity of the piping system. Material visually appears to be lead-containing and bell and spigot joints are known to contain lead solder		Assumed	



Description / Location of Material	Condition	Lead Concentration (ppm)	Sample Number	Lead-Containing (Yes/No)	Photograph
White wall paint – Present on walls from the basement to the fourth floor	Fair	154	Historical EHSP Report: 04-0068- 12-001  LBP-D	Yes	
Grey floor paint – Present within the basement and on the east and west stairs	Fair	1955	Historical EHSP Report: 04-0068- 12-001  LBP-G	Yes	



Description / Location of Material	Condition	Lead Concentration (ppm)	Sample Number	Lead-Containing (Yes/No)	Photograph
Yellow paint – Present on brick in various areas from the basement to the third floor	Fair	1243	Historical EHSP Report: 04-0068-12-001  LBP-J	Yes	

**Notes:** (1) "N/A" indicates not applicable. Sampled paint contains less than laboratory reporting detection limit and is not considered to be a lead-containing paint (LCP).

[https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/appendix c - spreadsheet of findings - jlr.docx](https://golderassociates.sharepoint.com/sites/21338g/deliverables/dsr/appendix%20c%20-%20spreadsheet%20of%20findings%20-%20jlr.docx)



**APPENDIX D**

# Laboratory Test Reports





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800267  
Customer ID: 55GOLA78  
Customer PO:  
Project ID:

**Attn:** Kyle Heagle  
Golder Associates, Ltd.  
1931 Robertson Road  
Ottawa, ON K2H 5B7

**Phone:** (613) 592-9600  
**Fax:** (613) 592-9601  
**Collected:**  
**Received:** 2/02/2018  
**Analyzed:** 2/09/2018

**Proj:** 1791616

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** 1A **Lab Sample ID:** 671800267-0001

**Sample Description:** BLACK TAR ON WALLS IN MECH 005

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Black	0%	100%	None Detected	

**Client Sample ID:** 1B **Lab Sample ID:** 671800267-0002

**Sample Description:** BLACK TAR ON WALLS IN MECH 005

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Black	0%	100%	None Detected	

**Client Sample ID:** 1C **Lab Sample ID:** 671800267-0003

**Sample Description:** BLACK TAR ON WALLS IN MECH 005

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Black	0%	75%	25% Chrysotile	

**Client Sample ID:** 2A-Caulk **Lab Sample ID:** 671800267-0004

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Red	0%	100%	None Detected	

**Client Sample ID:** 2A-Parging **Lab Sample ID:** 671800267-0004A

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	35%	65% Chrysotile	

**Client Sample ID:** 2B-Caulk **Lab Sample ID:** 671800267-0005

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Red	0%	100%	None Detected	

**Client Sample ID:** 2B-Parging **Lab Sample ID:** 671800267-0005A

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	35%	65% Chrysotile	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800267  
Customer ID: 55GOLA78  
Customer PO:  
Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** 2C-Caulk **Lab Sample ID:** 671800267-0006

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Red	0%	100%	None Detected	

**Client Sample ID:** 2C-Parging **Lab Sample ID:** 671800267-0006A

**Sample Description:** RED CAULKING AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	35%	65% Chrysotile	

**Client Sample ID:** 3A **Lab Sample ID:** 671800267-0007

**Sample Description:** INFILL AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 3B **Lab Sample ID:** 671800267-0008

**Sample Description:** INFILL AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 3C **Lab Sample ID:** 671800267-0009

**Sample Description:** INFILL AROUND CHIMNEY PIPE IN MECH 002

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 4A **Lab Sample ID:** 671800267-0010

**Sample Description:** BLACK TAR PAPER BETWEEN TERRACOTTA AND BRICKS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown/Black	55%	45%	None Detected	

**Client Sample ID:** 4B **Lab Sample ID:** 671800267-0011

**Sample Description:** BLACK TAR PAPER BETWEEN TERRACOTTA AND BRICKS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Black	70%	30%	None Detected	

**Client Sample ID:** 4C **Lab Sample ID:** 671800267-0012

**Sample Description:** BLACK TAR PAPER BETWEEN TERRACOTTA AND BRICKS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Black	70%	30%	None Detected	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800267  
Customer ID: 55GOLA78  
Customer PO:  
Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** 5A **Lab Sample ID:** 671800267-0013  
**Sample Description:** FIBERBOARD IN CLASSROOMS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown	98%	2%	None Detected	

**Client Sample ID:** 5B **Lab Sample ID:** 671800267-0014  
**Sample Description:** FIBERBOARD IN CLASSROOMS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown	98%	2%	None Detected	

**Client Sample ID:** 5C **Lab Sample ID:** 671800267-0015  
**Sample Description:** FIBERBOARD IN CLASSROOMS

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown	98%	2%	None Detected	

**Client Sample ID:** 6A **Lab Sample ID:** 671800267-0016  
**Sample Description:** FIBERBOARD BEHIND PLASTER IN ENTRANCES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown/Black	98%	2%	None Detected	

**Client Sample ID:** 6B **Lab Sample ID:** 671800267-0017  
**Sample Description:** FIBERBOARD BEHIND PLASTER IN ENTRANCES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown/Black	98%	2%	None Detected	

**Client Sample ID:** 6C **Lab Sample ID:** 671800267-0018  
**Sample Description:** FIBERBOARD BEHIND PLASTER IN ENTRANCES

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Brown	98%	2%	None Detected	

**Client Sample ID:** 7A **Lab Sample ID:** 671800267-0019  
**Sample Description:** EXTERIOR BRICK MORTAR FROM STAGE AREA

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 7B **Lab Sample ID:** 671800267-0020  
**Sample Description:** EXTERIOR BRICK MORTAR FROM STAGE AREA

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Gray	0%	100%	None Detected	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800267  
Customer ID: 55GOLA78  
Customer PO:  
Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: 7C

Lab Sample ID: 671800267-0021

Sample Description: EXTERIOR BRICK MORTAR FROM STAGE AREA

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Pink	0%	100%	None Detected	

Client Sample ID: 8A

Lab Sample ID: 671800267-0022

Sample Description: EXTERIOR CAULKING AROUND DOOR LOCATED ON THE SOUTH WEST SIDE OF THE  
STAGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Beige	0%	96%	4% Chrysotile	

Client Sample ID: 8B

Lab Sample ID: 671800267-0023

Sample Description: EXTERIOR CAULKING AROUND DOOR LOCATED ON THE SOUTH WEST SIDE OF THE  
STAGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Beige	0%	96%	4% Chrysotile	

Client Sample ID: 8C

Lab Sample ID: 671800267-0024

Sample Description: EXTERIOR CAULKING AROUND DOOR LOCATED ON THE SOUTH WEST SIDE OF THE  
STAGE

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/09/2018	Beige	0%	96%	4% Chrysotile	

### Analyst(s):

Ewa Krupinska PLM (9)  
Simon Parent PLM (18)

### Reviewed and approved by:

Simon Parent, Laboratory Manager  
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON

Initial report from: 02/09/2018 12:58:17





**EMSL CANADA, INC.**  
LABORATORY • PRODUCTS • TRAINING

# Asbestos Chain of Custody

**EMSL Order Number (Lab Use Only):**

671800267

EMSL CANADA, INC.  
22 ANTARES DRIVE, SUITE 102  
OTTAWA, ON, K2E 7Z6  
PHONE: (343) 882-6076  
FAX: (343) 882-6077

<b>Company : Golder Associates Ltd</b>		<b>EMSL-Bill to:</b> <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different <small>If Bill to is Different note instructions in Comments**</small>	
<b>Street: 1931 Robertson Road</b>		<i>Third Party Billing requires written authorization from third party</i>	
<b>City: Ottawa</b>	<b>State/Province: ON</b>	<b>Zip/Postal Code: K2H 5B7</b>	<b>Country: Canada</b>
<b>Report To (Name): Kyle Heagle</b>		<b>Fax #:</b>	
<b>Telephone #: 613-295-1391</b>		<b>Email Address: kyle_heagle@golder.com</b>	
<b>Project Name/Number: 1791616</b>			
<b>Please Provide Results:</b> <input type="checkbox"/> Fax <input type="checkbox"/> Email		<b>Purchase Order:</b>	
		<b>U.S. State Samples Taken:</b>	
<b>Turnaround Time (TAT) Options* – Please Check</b>			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input checked="" type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
<small>*For TEM Air 3 hours through 6 hours, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.</small>			
<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr. TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <i>0-5</i> <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> IRSST 244-3 PLM/TEM <input type="checkbox"/> NIOSH 9002 (<1%)		<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water:</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
		<b>TEM- Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> EPA Protocol (Semi-Quantitative) <input type="checkbox"/> EPA Protocol (Quantitative) <b>Other:</b>	
<input type="checkbox"/> Check For Positive Stop – Clearly Identify Homogenous Group		Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8µm <input type="checkbox"/> 0.45µm	
<b>Samplers Name: Kyle Heagle</b>		<b>Samplers Signature:</b> <i>Kyle Heagle</i>	
<b>Sample #</b>	<b>Sample Description</b>	<b>Volume/Area (Air) HA # (Bulk)</b>	<b>Date/Time Sampled</b>
1A - 1C	Black Tar on walls in Mech 005		
2A - 2C	Red Caulking around chimney pipe in Mech 002		
3A-3C	Infill around chimney Pipe in Mech 002		
4A-4C	Black Tar Paper between Terracotta and Bricks		
5A-5C	Fiberboard in classrooms		
6A-6C	Fiberboard behind plaster in entrances		
7A-7C	Exterior Brick Mortar from stage area		
8A-8C	Exterior caulking around door located on the south west side of the stage		
<b>Client Sample # (s): 1A-1C - 8A-8C</b>		<b>Total # of Samples: 24</b>	
<b>Relinquished (Client): Kyle Heagle</b>		<b>Date: Feb 2, 2018</b>	<b>Time: 10:00 am</b>
<b>Received (Lab): <i>Provisional Ottawa</i></b>		<b>Date: 2/2/18</b>	<b>Time: 12:40pm</b>
<b>Comments/Special Instructions:</b>			





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800348  
Customer ID: 55GOLA78  
Customer PO: 1791616  
Project ID:

**Attn:** Kyle Heagle  
Golder Associates, Ltd.  
1931 Robertson Road  
Ottawa, ON K2H 5B7

**Phone:** (613) 592-9600  
**Fax:** (613) 592-9601  
**Collected:**  
**Received:** 2/14/2018  
**Analyzed:** 2/15/2018

**Proj:** 1791616

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** 9A-Skim Coat **Lab Sample ID:** 671800348-0001

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	98%	2% Chrysotile	

**Client Sample ID:** 9A-Base Coat **Lab Sample ID:** 671800348-0001A

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	1%	99%	None Detected	

**Client Sample ID:** 9B-Skim Coat **Lab Sample ID:** 671800348-0002

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	98%	2% Chrysotile	

**Client Sample ID:** 9B-Base Coat **Lab Sample ID:** 671800348-0002A

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	1%	99%	None Detected	

**Client Sample ID:** 9C-Skim Coat **Lab Sample ID:** 671800348-0003

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	96%	4% Chrysotile	

**Client Sample ID:** 9C-Base Coat **Lab Sample ID:** 671800348-0003A

**Sample Description:** East Stairwell Plaster First floor to first landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	1%	99%	None Detected	

**Client Sample ID:** 10A-Skim Coat **Lab Sample ID:** 671800348-0004

**Sample Description:** East Stairwell Plaster First landing second stairs to top of second landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	96%	4% Chrysotile	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
 Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800348  
 Customer ID: 55GOLA78  
 Customer PO: 1791616  
 Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

<b>Client Sample ID:</b> 10A-Base Coat		<b>Lab Sample ID:</b> 671800348-0004A				
<b>Sample Description:</b> East Stairwell Plaster First landing second stairs to top of second landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> 10B-Skim Coat		<b>Lab Sample ID:</b> 671800348-0005				
<b>Sample Description:</b> East Stairwell Plaster First landing second stairs to top of second landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	96%	4% Chrysotile	
<b>Client Sample ID:</b> 10B-Base Coat		<b>Lab Sample ID:</b> 671800348-0005A				
<b>Sample Description:</b> East Stairwell Plaster First landing second stairs to top of second landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> 10C-Skim Coat		<b>Lab Sample ID:</b> 671800348-0006				
<b>Sample Description:</b> East Stairwell Plaster First landing second stairs to top of second landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	96%	4% Chrysotile	
<b>Client Sample ID:</b> 10C-Base Coat		<b>Lab Sample ID:</b> 671800348-0006A				
<b>Sample Description:</b> East Stairwell Plaster First landing second stairs to top of second landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> 11A		<b>Lab Sample ID:</b> 671800348-0007				
<b>Sample Description:</b> East Stairwell Plaster Second floor to third landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	99%	1% Chrysotile	
<b>Client Sample ID:</b> 11B-Skim Coat		<b>Lab Sample ID:</b> 671800348-0008				
<b>Sample Description:</b> East Stairwell Plaster Second floor to third landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	98%	2% Chrysotile	
<b>Client Sample ID:</b> 11B-Base Coat		<b>Lab Sample ID:</b> 671800348-0008A				
<b>Sample Description:</b> East Stairwell Plaster Second floor to third landing						
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800348  
Customer ID: 55GOLA78  
Customer PO: 1791616  
Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** 11C-Skim Coat **Lab Sample ID:** 671800348-0009

**Sample Description:** East Stairwell Plaster Second floor to third landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	White	0%	98%	2% Chrysotile	

**Client Sample ID:** 11C-Base Coat **Lab Sample ID:** 671800348-0009A

**Sample Description:** East Stairwell Plaster Second floor to third landing

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 12A **Lab Sample ID:** 671800348-0010

**Sample Description:** Cementitious parging on basement walls

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	99%	1% Chrysotile	

**Client Sample ID:** 12B **Lab Sample ID:** 671800348-0011

**Sample Description:** Cementitious parging on basement walls

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 12C **Lab Sample ID:** 671800348-0012

**Sample Description:** Cementitious parging on basement walls

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 13A **Lab Sample ID:** 671800348-0013

**Sample Description:** Plaster from gym ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	

**Client Sample ID:** 13B **Lab Sample ID:** 671800348-0014

**Sample Description:** Plaster from gym ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	97%	3% Chrysotile	

**Client Sample ID:** 13C **Lab Sample ID:** 671800348-0015

**Sample Description:** Plaster from gym ceiling

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Gray	0%	100%	None Detected	





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671800348  
Customer ID: 55GOLA78  
Customer PO: 1791616  
Project ID:

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: 14A

Lab Sample ID: 671800348-0016

Sample Description: Tar paper along the east exterior of building

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Black	20%	80%	None Detected	

Client Sample ID: 14B

Lab Sample ID: 671800348-0017

Sample Description: Tar paper along the east exterior of building

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Black	25%	75%	None Detected	

Client Sample ID: 14C

Lab Sample ID: 671800348-0018

Sample Description: Tar paper along the east exterior of building

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	2/15/2018	Black	60%	40%	None Detected	

### Analyst(s):

Ewa Krupinska PLM (13)  
Simon Parent PLM (13)

### Reviewed and approved by:

Simon Parent, Laboratory Manager  
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON

Initial report from: 02/15/2018 12:29:39





EMSL CANADA, INC.  
LABORATORY • PRODUCTS • TRAINING

# Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

671800348

EMSL CANADA, INC.  
22 ANTARES DRIVE, SUITE  
102  
OTTAWA, ON, K2E 7Z6  
PHONE: 343-882-6076  
FAX: 343-882-6077

Company: <u>Golder Associates</u>		EMSL Customer ID:	
Street: <u>1931 Robertson Road</u>		City: <u>Ottawa</u>	
Zip/Postal Code: <u>K2H 5B7</u>	State/Province: <u>ON</u>	Country: <u>Canada</u>	
Telephone #: <u>613-295-1391</u>		Email Address: <u>Kyle_Heagle@golder.com</u>	
Project Name/Number: <u>1791616</u>		EMSL Project ID (Internal Use Only):	
Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email		Purchase Order:	State/Province Samples Taken:
EMSL-Bill to: <input type="checkbox"/> Same <input type="checkbox"/> Different - If Bill to is Different note instructions in Comments**			
Third Party Billing requires written authorization from third party			
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour	<input type="checkbox"/> 6 Hour	<input checked="" type="checkbox"/> 24 Hour	<input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week
*For TEM Air 3 hours through 6 hours, please call ahead to schedule. *There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.			
<b>PCM - Air</b> <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> IRSST PCM <b>PLM - Bulk (reporting limit) 0.5-1</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> 400 PTCT (<0.25%) <input type="checkbox"/> 1000 PTCT (<0.1%) <input type="checkbox"/> PLM EPA NOB (<1%) <input type="checkbox"/> 400 PTCT (<0.25%) <input type="checkbox"/> 1000 PTCT (<0.1%) <input type="checkbox"/> IRSST PLM <input type="checkbox"/> NIOSH 9002 (<1%) <input type="checkbox"/> Other		<b>TEM - Air</b> <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> IRRST TEM (NYS 198.4) <b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <b>TEM - Water</b> <input type="checkbox"/> EPA 100.2 (All fibre sizes) <input type="checkbox"/> EPA 100.2 (Fibres >10µm)	
		<b>Soil/Rock/Vermiculite</b> <input type="checkbox"/> PLM EPA 600/R-93/116 with milling prep (<0.25%) <input type="checkbox"/> PLM EPA 600/R-93/116 with milling prep (<0.1%) <input type="checkbox"/> TEM EPA 600/R-93/116 with milling prep (<0.1%) <input type="checkbox"/> TEM EPA 600/R-93/116 with milling prep (<0.01%) <input type="checkbox"/> ASTM D7521 Sieve Method <input type="checkbox"/> TEM Qualitative via Filtration Prep <input type="checkbox"/> TEM Qualitative via Drop Mount Prep <input type="checkbox"/> Cincinnati Method EPA 600/R-04/004 - PLM/TEM* *(required for vermiculite in BC and NS)	
		<b>Asphalt</b> <input type="checkbox"/> PLM EPA Gravimetric with milling prep (<0.25%)	
<input type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Groups		Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8µm <input type="checkbox"/> 0.45µm	
Samplers Name: <u>Kyle Heagle</u>		Sampler's Signature: <u>Kyle Heagle</u>	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
9A-9C	East Stairwell Plaster First floor to first landing		
10A-10C	East Stairwell Plaster First landing to top of second landing		
11A-11C	East Stairwell Plaster Second floor to third landing		
12A-12C	Cementitious parging on basement walls		
13A-13C	Plaster from gym ceiling		
14A-14C	Tar paper along the east exterior of building		
Client Sample #(s): <u>9A-9C</u> - <u>14A-14C</u>		Total # of Samples: <u>18</u>	
Relinquished (Client): <u>Kyle Heagle</u>		Date: <u>Feb 14, 2018</u>	Time: <u>1:03</u>
Received (Lab): <u>Shawna Haddad</u>		Date: <u>2/17/18</u>	Time: <u>1:03 PM</u>
Comments/Special Instructions:			



**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: 289-997-4602 / (289) 997-4607

<http://www.EMSL.com>[torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Or 551801364

CustomerID: 55GOLA78

CustomerPO: 1791616

ProjectID:

Attn: **Kyle Heagle**  
**Golder Associates, Ltd.**  
**1931 Robertson Road**  
**Ottawa, ON K2H 5B7**

Phone: (613) 592-9600  
Fax: (613) 592-9601  
Received: 02/05/18 11:31 AM  
Collected:

Project: 1791616

**Test Report: Lead in Paint Chips by Flame AAS (SW 846 3051A/7000B)\***

<i>Client Sample Description</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight</i>	<i>RDL</i>	<i>Lead Concentration</i>
LP#1 551801364-0001		2/6/2018	0.2279 g	88 ppm	<88 ppm
Site: BLUE FLOOR PAINT					

Rowena Fanto, Lead Supervisor  
or other approved signatory

\*Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.010% wt based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. "<" (less than) result signifies the analyte was not detected at or above the warning limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements unless specifically indicated otherwise. Definitions of modifications are available upon request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON

Initial report from 02/12/2018 08:31:59





## Lead (Pb) Chain of Custody

EMSL Order ID (Lab Use Only):

551801364

EMSL CANADA, INC.  
10 FALCONER DRIVE UNIT #3  
MISSISSAUGA, ON L5N 3L8  
PHONE: (289) 997-4602  
FAX: (289) 997-4607


Company : Golder Associates		EMSL-Bill to: <input type="checkbox"/> Same <input type="checkbox"/> Different If Bill to is Different note instructions in Comments**	
Street: 1931 Robertson Rd		Third Party Billing requires written authorization from third party	
City: Ottawa	State/Province: ON	Zip/Postal Code: K2H 5B7	Country: Canada
Report To (Name): Kyle Heagle		Telephone #: 613-592-9600	
Email Address: kyle_heagle@golder.com		Fax #:	Purchase Order:
Project Name/Number: 1791616		Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email	
U.S. State Samples Taken:		CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt	
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour	<input type="checkbox"/> 6 Hour	<input type="checkbox"/> 24 Hour	<input type="checkbox"/> 48 Hour
<input type="checkbox"/> 72 Hour	<input type="checkbox"/> 96 Hour	<input checked="" type="checkbox"/> 1 Week	<input type="checkbox"/> 2 Week
*Analysis completed in accordance with EMSL's Terms and Conditions located in the Price Guide			
Matrix	Method	Instrument	Reporting Limit
Chips <input type="checkbox"/> % by wt. <input type="checkbox"/> mg/cm <sup>2</sup> <input checked="" type="checkbox"/> ppm	SW846-7000B	Flame Atomic Absorption	0.01%
Air	NIOSH 7082	Flame Atomic Absorption	4 µg/filter
	NIOSH 7105	Graphite Furnace AA	0.03 µg/filter
	NIOSH 7300 modified	ICP-AES/ICP-MS	0.5 µg/filter
Wipe* <input type="checkbox"/> ASTM <input type="checkbox"/> non ASTM <input type="checkbox"/> *If no box is checked, non-ASTM Wipe is assumed	SW846-7000B	Flame Atomic Absorption	10 µg/wipe
	SW846-6010B or C	ICP-AES	1.0 µg/wipe
	SW846-7000B/7010	Graphite Furnace AA	0.075 µg/wipe
TCLP	SW846-1311/7000B/SM 3111B	Flame Atomic Absorption	0.4 mg/L (ppm)
	SW846-1131/SW846-6010B or C	ICP-AES	0.1 mg/L (ppm)
Soil	SW846-7000B	Flame Atomic Absorption	40 mg/kg (ppm)
	SW846-7010	Graphite Furnace AA	0.3 mg/kg (ppm)
	SW846-6010B or C	ICP-AES	2 mg/kg (ppm)
Wastewater Unpreserved <input type="checkbox"/> Preserved with HNO <sub>3</sub> pH < 2 <input type="checkbox"/>	SM3111B/SW846-7000B	Flame Atomic Absorption	0.4 mg/L (ppm)
	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)
	EPA 200.7	ICP-AES	0.020 mg/L (ppm)
Drinking Water Unpreserved <input type="checkbox"/> Preserved with HNO <sub>3</sub> pH < 2 <input type="checkbox"/>	EPA 200.9	Graphite Furnace AA	0.003 mg/L (ppm)
	EPA 200.8	ICP-MS	0.001 mg/L (ppm)
TSP/SPM Filter	40 CFR Part 50	ICP-AES	12 µg/filter
	40 CFR Part 50	Graphite Furnace AA	3.6 µg/filter
Other:			
Name of Sampler: Kyle Heagle		Signature of Sampler: <i>Kyle Heagle</i>	
Sample #	Location	Volume/Area	Date/Time Sampled
LP#1	Blue Floor Paint		
Client Sample #'s	LP1 - LP1	Total # of Samples:	1
Relinquished (Client):	Kyle Heagle	Date:	Feb 2, 2017
Received (Lab):		Date:	
Comments:			



## APPENDIX E

# Figures





KEY MAP



SCALE 1:25,000

LEGEND

- APPROXIMATE ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
- APPROXIMATE NON-ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
- CONFIRMED AREAS OF REMAINING ASBESTOS-CONTAINING MATERIALS**
  - REMAINING 25% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING BLACK TAR ON WALLS
  - REMAINING 1% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING CEMENTITIOUS PARGING ON WALLS

NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

REFERENCE(S)

- FLOOR PLAN PROVIDED BY CLIENT IN AUTOCAD FORMAT.
- PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83.
- COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

CLIENT  
J.L. RICHARDS & ASSOCIATES LIMITED

PROJECT  
DESIGNATED SUBSTANCES REVIEW  
LA MAISON DE LA FRANCOPHONIE D'OTTAWA  
2720 RICHMOND ROAD, OTTAWA

TITLE  
**SAMPLE LOCATION PLAN, BASEMENT**


CONSULTANT	YYYY-MM-DD	2018-02-22
DESIGNED	KH	
PREPARED	BR	
REVIEWED	TAS	
APPROVED	TAS	



PROJECT NO. 1791616 CONTROL 0001 REV. 0 FIGURE 1



Path: N:\Active\Spatial\_MCE\ECQ\2720\_Richmond\_Rd\_Ottawa\99\_PROJ\1791616\_L1R\_DSR40\_PROD\0001\_L1S\_DSR\1791616-0001-HS-0002.mxd



SCALE 1:25,000

- LEGEND**
- APPROXIMATE ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
  - APPROXIMATE NON-ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
- CONFIRMED AREAS OF REMAINING ASBESTOS-CONTAINING MATERIALS**
- ASSUMED ASBESTOS-CONTAINING MATERIAL PRESENT WITHIN BELL AND SPIGOT JOINTS (MULTIPLE JOINTS AT EACH LOCATION)
  - REMAINING 65%-90% CHRYSOTILE FRIABLE ASBESTOS-CONTAINING ELBOW AND PIPE INSULATION
  - REMAINING 1%-4% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING WALL PLASTER
  - REMAINING 1%-4% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING BULKHEADS
  - REMAINING 1%-3% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING CEILING PLASTER
  - REMAINING 1%-3% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING CEILING DOUBLE LAYER OF PLASTER

**NOTE(S)**  
1. ALL LOCATIONS ARE APPROXIMATE

**REFERENCE(S)**  
1. FLOOR PLAN PROVIDED BY CLIENT IN AUTOCAD FORMAT.  
2. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83.  
COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28



CLIENT J.L. RICHARDS & ASSOCIATES LIMITED		
PROJECT DESIGNATED SUBSTANCES REVIEW LA MAISON DE LA FRANCOPHONIE D'OTTAWA 2720 RICHMOND ROAD, OTTAWA		
TITLE SAMPLE LOCATION PLAN, GROUND FLOOR		
CONSULTANT	YYYY-MM-DD	2018-02-22
	DESIGNED	KH
	PREPARED	BR
	REVIEWED	TAS
	APPROVED	TAS
PROJECT NO. 1791616	CONTROL 0001	REV. 0
		FIGURE 2



IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 28mm



P:\01 - N\Active\Spatial - MCE\ECQ 2720 - Richmond\_Rd\_Ottawa\99\_PROJ\1791616\_11\_R\_DSR\40\_PROD\0001\_115\_DSR\1791616-0001-HS-0093.mxd




SCALE 1:25,000

- LEGEND**
- APPROXIMATE ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
  - APPROXIMATE NON-ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
- CONFIRMED AREAS OF REMAINING ASBESTOS-CONTAINING MATERIALS**
- ASSUMED ASBESTOS-CONTAINING MATERIAL PRESENT WITHIN BELL AND SPIGOT JOINTS (MULTIPLE JOINTS AT EACH LOCATION)
  - REMAINING 65%-90% CHRYSOTILE FRIABLE ASBESTOS-CONTAINING ELBOW AND PIPE INSULATION
  - REMAINING 1%-4% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING WALL PLASTER
  - ASSUMED TO BE CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING WALL PLASTER
  - REMAINING 1%-3% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING CEILING PLASTER

**NOTE(S)**  
1. ALL LOCATIONS ARE APPROXIMATE


**REFERENCE(S)**  
1. FLOOR PLAN PROVIDED BY CLIENT IN AUTOCAD FORMAT.  
2. PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83.  
COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

CLIENT J.L. RICHARDS & ASSOCIATES LIMITED		
PROJECT DESIGNATED SUBSTANCES REVIEW LA MAISON DE LA FRANCOPHONIE D'OTTAWA 2720 RICHMOND ROAD, OTTAWA		
TITLE SAMPLE LOCATION PLAN, SECOND FLOOR		
CONSULTANT	YYYY-MM-DD	2018-02-22
	DESIGNED	KH
	PREPARED	BR
	REVIEWED	TAS
	APPROVED	TAS
PROJECT NO. 1791616	CONTROL 0001	REV. 0
		FIGURE 3

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM:  
25mm



P:\ht\N\Active\Spatial\MCEPECQ2720\_Richmond\_Rd\_Ottawa\99\_PROJ\1791616\_L1R\_DSRA4L\_PROD\0001\_LHS\_DSRA4L\_PROD\0001\_LHS-0004.mxd



#### KEY MAP



SCALE 1:25,000

#### LEGEND

- APPROXIMATE ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
  - APPROXIMATE NON-ASBESTOS-CONTAINING MATERIAL SAMPLE LOCATION
  - APPROXIMATE NON-LEAD-CONTAINING PAINT SAMPLE LOCATION
- CONFIRMED AREAS OF REMAINING ASBESTOS-CONTAINING MATERIALS**
- ASSUMED ASBESTOS-CONTAINING MATERIAL PRESENT WITHIN BELL AND SPIGOT JOINTS (MULTIPLE JOINTS AT EACH LOCATION)
  - REMAINING 1%-4% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING WALL PLASTER
  - REMAINING 1%-3% CHRYSOTILE NON-FRIABLE ASBESTOS-CONTAINING CEILING PLASTER

#### NOTE(S)

1. ALL LOCATIONS ARE APPROXIMATE

#### REFERENCE(S)

- FLOOR PLAN PROVIDED BY CLIENT IN AUTOCAD FORMAT.
- PROJECTION: TRANSVERSE MERCATOR, DATUM: NAD 83, COORDINATE SYSTEM: MTM ZONE 9, VERTICAL DATUM: CGVD28

#### CLIENT

J.L. RICHARDS & ASSOCIATES LIMITED

#### PROJECT

DESIGNATED SUBSTANCES REVIEW  
LA MAISON DE LA FRANCOPHONIE D'OTTAWA  
2720 RICHMOND ROAD, OTTAWA

#### TITLE

SAMPLE LOCATION PLAN, THIRD FLOOR

#### CONSULTANT



YYYY-MM-DD 2018-02-22

DESIGNED KH

PREPARED BR

REVIEWED TAS

APPROVED TAS

PROJECT NO.  
1791616

CONTROL  
0001

REV.  
0

FIGURE

4

IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: 25mm



**APPENDIX F**

## Reference Reports





---

# Centre Multiservices Francophone de l'Ouest d'Ottawa

---

Designated Substances Survey  
2720 Richmond Road  
Ottawa, Ontario

---

April 2012  
EHS<sup>p</sup> Project No.: 04-0068-12-001

---





**DESIGNATED SUBSTANCES SURVEY REPORT  
2720 RICHMOND ROAD  
OTTAWA, ON**

**EHS Project No.: 04-0068-12-001**

Prepared by:  
EHS Partnerships Ltd.  
406 – 2 Gurdwara Road  
Ottawa, ON K2E 1A2

For:

Mr. Bernard Benoit  
CMFO c/o Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent, Unit B4  
Ottawa, ON.  
K1B 5N1

April 2012

Prepared by:

Geoff Leclair, A.Sc.T  
Project Coordinator

Reviewed by:

Trent Windsor, C.E.T.  
Associate

<b>CONFIDENTIAL</b>
---------------------

Distribution:

2 Copies (1 PDF & 1 hard copy) – BBPM Inc.  
1 Copy – EHS Partnerships Ltd.



## **EXECUTIVE SUMMARY**

EHS Partnerships Ltd. (EHS<sup>p</sup>) was commissioned by BBPM Project Managers on behalf of the Centre Multiservices Francophone de l'Ouest d'Ottawa (CMFO) to complete a Designated Substances Survey (DSS) of the property located at 2720 Richmond Road in Ottawa, Ontario (Site). The survey was requested to satisfy Section 30 of the Occupational Health and Safety Act and Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (O.Reg. 278/05) in order to identify any designated and hazardous materials that may be present at the site.

EHS<sup>p</sup> personnel completed the site reconnaissance on April 4, 2012. Based on the findings of the visual inspection, suspect materials were documented, collected and subsequently submitted for analysis at a 3<sup>rd</sup> party analytical laboratory.

## **FINDINGS**

### **Asbestos**

Asbestos was detected in sampled plaster, drywall joint compound, vinyl flooring, thermal insulation, ceiling tile and mastic at the site. Potential asbestos containing materials observed at the Site and not sampled include roofing materials, caulking, glue-on ceiling tile mastic, and gymnasium ceiling panels located in the main building. All asbestos containing material (ACM) and potential ACM was observed to be in good condition during the DSS and do not currently pose a hazard to occupants, workers, and others unless this material is damaged or disturbed without using the proper engineering controls. See Section 6.0.

### **Benzene**

Benzene was not observed at the site; however, there may be a potential exposure hazard to occupants, workers, or others if plastic or rubber materials are exposed to excessive heat.

### **Lead**

Lead was detected in all the paint chip samples collected at the Site. Painted surfaces were observed to be in good to poor condition and may pose an exposure risk to occupants, workers, or others if paint is disturbed without taking the proper precautions. Lead may also be present in the solder joints of the copper piping observed throughout the site. See Section 7.0.

### **Mercury**

Mercury vapour is present in fluorescent light tubes located throughout the Site. Mercury at the site does not pose a risk to site occupants, workers, or others if these materials are handled and disposed of with care.

### **Mould**

Visible potential mould growth was observed during the DSS in the main building outside of the fan room. Evidence of significant moisture intrusion was observed throughout the Site in the basement.



Moisture proofing elements of the foundation may have degraded overtime resulting in significant water infiltration. The conditions at the Site are potentially hazardous to occupants, workers, or others.

### **Polychlorinated Biphenyls (PCBs)**

PCB's may be present in light ballasts at the Site. PCB containing ballasts do not pose a hazard to Site occupants, workers, or others if they are handled and disposed of using proper procedures.

### **Silica**

Silica is present in the concrete, terrazzo, mortar, brick, asphalt, plaster, drywall joint compound, foundation parging, vinyl flooring, ceramic tiles, and cementitious parging observed at the site. Silica containing materials were observed to be in good condition at the time of the DSS and do not currently pose a hazard to occupants, workers, or others unless these materials are damaged or disturbed without using proper engineering controls.

### **Vinyl Chloride**

Vinyl Chloride was not observed at the site; however there is a potential exposure hazard to occupants, workers, or others if Polyvinyl Chloride (PVC) pipes and wire coatings are exposed to excessive heat.

### **Other Designated Substances and Hazardous Materials**

Arsenic, Acrylonitrile, Isocyanates, Coke Oven Emissions, and Ethylene Oxide, were not observed at the site.



## TABLE OF CONTENTS

EXECUTIVE SUMMARY .....	i
1.0 INTRODUCTION .....	1
2.0 SITE DESCRIPTION.....	1
3.0 OBJECTIVE .....	1
4.0 SCOPE.....	1
5.0 DESIGNATED SUBSTANCE SURVEY METHODOLOGY AND RESULTS .....	1
5.1 Acrylonitrile.....	2
5.2 Arsenic .....	2
5.3 Asbestos .....	2
5.4 Benzene.....	2
5.5 Coke Oven Emissions.....	3
5.6 Ethylene Oxide .....	3
5.7 Isocyanates.....	3
5.8 Lead .....	3
5.9 Mercury .....	3
5.10 Silica .....	4
5.11 Vinyl Chloride.....	4
6.0 ASBESTOS CONTAINING MATERIALS SURVEY .....	4
6.1 General.....	4
6.2 Findings.....	4
7.0 LEAD BASED PAINT SURVEY.....	12
7.1 General.....	12
7.2 Findings.....	12
8.0 HAZARDOUS MATERIALS SURVEY .....	13
8.1 General.....	13
8.2 Polychlorinated Biphenyls.....	13
8.3 Mould.....	13
9.0 CONCLUSIONS AND RECOMMENDATIONS .....	14
10.0 LIMITATIONS .....	16

## LIST OF TABLES

Table 1: Summary of Laboratory Analytical Results - Asbestos Containing Materials.....	5
Table 2: Summary of Laboratory Analytical Results - Lead Paint.....	12

## LIST OF APPENDICES

Appendix A: Photolog	
Appendix B: Analytical Results	



## **1.0 INTRODUCTION**

EHS Partnerships (EHS<sup>p</sup>) was retained by Mr. Bernard Benoit of the Centre Multiservices Francophone de l'Ouest d'Ottawa (CMFO) c/o BBPM Inc. to conduct a Designated and Hazardous Substances Survey (DSS) at the property located at 2720 Richmond Road, Ottawa, Ontario (Site). This report details the results of the DSS completed at the site on April 4, 2012.

## **2.0 SITE DESCRIPTION**

The Site consists of a two-storey main building and a one-storey annex building which were constructed in the 1920's and 1949 respectively. The main building includes a basement and the annex is slab on grade. The exterior of the buildings are finished with brick and mortar, and various roofing systems including asphalt. The interior walls and ceilings are comprised plaster, concrete, and some drywall. The flooring observed during the DSS consists of concrete, terrazzo, vinyl, and carpet. Various types of ceiling tiles were observed throughout the Site.

## **3.0 OBJECTIVE**

The survey was requested to satisfy Section 30 of the Occupational Health and Safety Act (OHSA) and Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (O.Reg. 278/05) in order to identify any designated and hazardous materials that may be present at the site.

## **4.0 SCOPE**

The scope of work included the following activities:

- Preparation of a Health and Safety Plan (HASP) prior to conducting the field work;
- Inspection and sampling of potential hazardous materials within the buildings in areas that could be reasonably accessed by field personnel;
- Documenting the location of potential hazardous materials and estimating quantities;
- Submission of representative samples of potential hazardous materials for laboratory analysis; and the
- Preparation of a report summarizing the designated substances survey.

## **5.0 DESIGNATED SUBSTANCE SURVEY METHODOLOGY AND RESULTS**

The field survey included the visual identification of potential designated substances and collection of samples for laboratory analysis to confirm the absence/presence of hazardous materials.

Designated substances in Ontario are defined in accordance with OHSA as a biological, chemical, or physical agent or combination thereof as a designated substance to which the exposure of a worker is prohibited, regulated, restricted, limited or controlled. Under section 30 of OHSA – "Duty of Project Owners", owners are required to determine if designated substances are present at a project site and disclose this information to project participants.

Designated substances that individuals are likely to be exposed to during construction projects include asbestos, lead, and silica. The Ontario Ministry of Labour provides guidance regarding these substances during construction in the following documents:



1. Ontario Regulation 278/05 (O.Reg. 278/05) – Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations.
2. Guideline – Silica on Construction Projects, Ministry of Labour 2004.
3. Guideline – Lead on Construction Projects, Ministry of Labour 2004.

The following sections provide an overview of the regulated designated substances and the potential presence of such substances at the site.

### **5.1 Acrylonitrile**

Acrylonitrile is a chemical compound that exists as a clear pungent smelling liquid. Acrylonitrile is an important compound used in the production of other chemicals and products.

This designated substance is highly flammable and toxic. When burned it releases hazardous compounds into the air including hydrogen sulfide which has been used in chemical warfare.

Based on EHS<sup>p</sup> observations Acrylonitrile was not identified at the site during the DSS.

### **5.2 Arsenic**

Arsenic is chemical element that occurs in several different minerals in nature. Arsenic is used in a wide variety of applications including the strengthening of steel and copper alloys, it is a valuable semiconductor, and has been used in the production of herbicides and pesticides.

Arsenic is a known human carcinogen and potent poison.

Based on EHS<sup>p</sup> observations Arsenic was not identified at the site during the DSS.

### **5.3 Asbestos**

Asbestos is a group of naturally occurring mineral silicates that has been used in the manufacture of building materials due to their desirable physical properties. Asbestos was used in a number of building materials such as roofing shingles, acoustic ceiling tile, vinyl flooring, cement products, insulation and other applications.

The association between the inhalation of asbestos fibres and various respiratory diseases is undisputed.

An asbestos containing material (ACM) survey was conducted by EHS<sup>p</sup> as part of this DSS. Details of the ACM survey are presented in section 6.0.

### **5.4 Benzene**

Benzene is natural compound found in petroleum based products such as gasoline and diesel fuels, asphalt and other hydrocarbon based products. It is used as a catalyst in various chemical processes including the production of plastics, rubber, drugs and pesticides.

Benzene is a known human carcinogen. Exposure to airborne benzene has been linked to various forms of leukemia.

Benzene was not observed at the site; however, there may be a potential exposure hazard to occupants, workers, or others if plastic or rubber materials are exposed to excessive heat.



## **5.5 Coke Oven Emissions**

Coke Oven Emissions are the airborne by-product resulting from the distillation of low-ash and sulfur coal or coke. Coke is a useful fuel, chemical reducer, and is even used in the production of Scotch whisky.

Coke oven emissions potentially cause lung and skin cancers.

Based on EHS<sup>p</sup> observations coke oven emissions are not present at the site.

## **5.6 Ethylene Oxide**

Ethylene Oxide is a colourless gas with a faint sweet odour. This organic compound has various applications in the chemical engineering industry.

Ethylene oxide is a known human carcinogen and poison. Chronic exposure is known to cause genetic mutations (damage caused to DNA resulting in physical mutations).

Based on observations noted during the DSS and historical use of the site, ethylene oxide is not present.

## **5.7 Isocyanates**

Isocyanates are any organic compound that contains a specific chemical functional group made up of a specific structure of one atom of nitrogen, carbon, and oxygen. The presence of this functional group gives chemical compounds unique properties that may be exploited in the production of polymers. Isocyanate containing polymers are used in the manufacture of paints, foams, and electrical insulation.

All isocyanates must be treated as highly hazardous with inhalation being the primary exposure hazard.

Based on observations noted during the DSS and historical use of the site, isocyanates are not present.

## **5.8 Lead**

Lead is a chemical element that is a soft malleable metal. Lead is used in the production of a number of products including ammunition, batteries, pipes, and paint.

Lead is potent neurotoxin that accumulates in the body and results in brain and nervous system damage. The primary routes of exposure to lead include inhalation and ingestion.

EHS<sup>p</sup> conducted a lead-based paint sampling program as part of the DSS. The findings of this sampling program are presented in section 7.0.

## **5.9 Mercury**

Mercury is a chemical element that is the only metal that exists in the liquid state at standard temperature and pressure. Elemental mercury has been used in a number of scientific instruments such as thermometers and barometers. In buildings liquid mercury has been used widely in thermostats and switch gear. Mercury vapour is used to produce light in fluorescent light tubes.

Chronic and acute inhalation of mercury vapour has been shown to have profound effects on the central nervous system including impaired cognitive skills, tremors, hallucinations, delirium, and suicidal tendency.



Mercury vapour is present in fluorescent light tubes observed throughout the Site.

### **5.10 Silica**

Silica is the common name for the chemical compound silicon dioxide that occurs naturally as sand or quartz. Due to the hardness of silica it has been used as the primary raw material in products such as glass, ceramics, and cement.

Inhalation of silica is known to cause irreversible lung diseases including cancer and silicosis.

Silica is present in the concrete, terrazzo, mortar, brick, asphalt, plaster, drywall joint compound, foundation parging, vinyl flooring, ceramic tiles, and cementitious parging observed at the site. If the aforementioned materials are to be disturbed, appropriate precautions should be taken during disturbance.

### **5.11 Vinyl Chloride**

Vinyl Chloride is a chemical compound that exists as a gas at standard temperature and pressure. It is used in the production of polyvinyl chloride (PVC) which is non-hazardous.

Vinyl chloride is a known human carcinogen and is known to cause liver damage.

Based on EHS<sup>p</sup> observations vinyl chloride is not present at the site; however there is the potential that vinyl chloride could be released if PVC pipes, plastic, or wire coatings are burnt.

## **6.0 ASBESTOS CONTAINING MATERIALS SURVEY**

### **6.1 General**

The asbestos containing materials (ACMs) survey was conducted by EHS<sup>p</sup> to satisfy Section 30 of the Occupational Health and Safety Act of Ontario and Ontario Regulation 278/05: Regulation Respecting Asbestos on Construction Projects and in Buildings and Repair Operations (O.Reg.278/05).

The ACMs survey was carried out in accordance with the measures prescribed in O.Reg.278/05.

### **6.2 Findings**

EHS<sup>p</sup> personnel completed site reconnaissance including visual inspection and sampling of potential ACMs on April 4, 2012. Based on the findings of the visual inspection, suspect materials were documented, collected and subsequently submitted for analysis at a 3<sup>rd</sup> party analytical laboratory.

As part of the ACMs survey, EHS<sup>p</sup> collected one hundred and thirty-six (136) representative samples from forty-two (42) distinct types of materials that were suspected to contain asbestos. Potential ACMs sampled during the DSS included plaster, vinyl flooring, cove base, mastic, drywall joint compound mortar, thermal insulation, caulking, roofing materials, foundation parging and other cementitious materials. Sampled materials were submitted using a chain of custody to Steve Moody Micro Services, of Farmers Branch, Texas. The analytical results are presented in Appendix B and are summarized in the following table:



**Table 1: Summary of Laboratory Analytical Results – Asbestos Containing Materials**

Sample ID	Material	Location	% Asbestos Concentration	Friability	Condition	Photo #
PL-1-A	Plaster	Annex – 004A	None Detected	Non-Friable	Good	1
PL-1-B		Annex – 001	2% Chrysotile			
PL-1-C		Annex-Teaching Lounge	Not Analyzed			
PL-1-D		Annex – Waiting				
PL-1-E		Annex – 002				
PL-1-F		Annex – 003				
PL-1-G		Annex – 004				
VT-1-A	Vinyl Floor Tile – Grey 1’x1’	Annex - 001	None Detected	Non-Friable	Good	2
VT-1-B						
VT-1-C						
VT-2-A	Vinyl Floor Tile – White 1’x1’	Annex - 001	None Detected	Non-Friable	Good	3
VT-2-B						
VT-2-C						
CB-A	Cove Base	Annex - 001	None Detected	Non-Friable	Good	4
CB-B						
CB-C						
CT-1-A	Ceiling Tile – 1’x 1’	Annex - 001	None Detected	Non-Friable	Good	5
CT-1-B						
CT-1-C						
DC-1-A	Drywall Joint Compound	Annex - 001	2% Chrysotile	Non-Friable	Good	6
DC-1-B		Annex - Waiting	Not Analyzed			
DC-1-C		Annex – Girls Washroom				



Sample ID	Material	Location	% Asbestos Concentration	Friability	Condition	Photo #
DC-1-D		Annex - 004				
DC-1-E		Annex - 004				
MT-1-A	Mortar – Concrete Block	Annex – Teachers Lounge	None Detected	Non- Friable	Good	7
MT-1-B						
MT-1-C						
VT-3-A	Vinyl Floor Tile – Yellow 9”x9”	Annex - Waiting	10% Chrysotile	Non- Friable	Good	8
VT-3-B			Not Analyzed			
VT-3-C						
VT-4-A	Vinyl Floor Tile – Black	Annex - Waiting	10% Chrysotile	Non- Friable	Good	9
VT-4-B			Not Analyzed			
VT-4-C						
PR-1-A	Fitting Insulation - Parging	Annex – Mechanical Room	65% Chrysotile	Friable	Good	10
PR-1-B			Not Analyzed			
PR-1-C						
PS-1-A	Pipe Straight Insulation – Corrugated Cardboard	Annex – Mechanical Room	90% Chrysotile	Friable	Good	11
PS-1-B			Not Analyzed			
PS-1-C						
TP-A	Pipe Straight Insulation – Sweat Wrap Tar Paper	Annex – Mechanical Room	5% Chrysotile	Non- Friable	Good	None
TP-B			Not Analyzed			
TP-C						
VT-5-A	Vinyl Floor Tile – Blue 1’x1’	Annex - 002	None Detected	Non- Friable	Good	13
VT-5-B						
VT-5-C						
CA-1-A	Black Caulking	Annex – Entrance Roof	None Detected	Non- Friable	Good	14
CA-1-B						
CA-1-C						
RC-A	Roofing Core Sample	Annex – Main Roof	None Detected	Non- Friable	Good	15
RC-B						
RC-C						
AS-A	Asphalt Shingle	Annex –	None Detected	Non-	Good	16



Sample ID	Material	Location	% Asbestos Concentration	Friability	Condition	Photo #
AS-B		Entrance Roof		Friable		
AS-C						
CA-2-A	Beige Caulking	Annex – Exterior	None Detected	Non-Friable	Good	17
CA-2-B						
CA-2-C						
TC-A	Trowelled Cementious Material	Annex – Exterior Windows	None Detected	Non-Friable	Good	18
TC-B						
TC-C						
FP-1-A	Foundation Parging	Annex – Exterior	None Detected	Non-Friable	Good	19
FP-1-B						
FP-1-C						
MR-1-A	Brick Mortar	Annex – Exterior	None Detected	Non-Friable	Good	20
MR-1-B						
MR-1-C						
PS-2-A	Pipe Straight Insulation – Corrugated Cardboard	Main – Lunch Room 018	90% Chrysotile	Friable	Good	21
PS-2-B			Not Analyzed			
PS-2-C						
PR-2-A	Pipe Fitting Insulation - Parging	Main – Lunch Room 018	65% Chrysotile	Friable	Good	22
PR-2-B		Main – Kitchen	Not Analyzed			
PR-2-C		Main – Boiler Room				
PS-3-A	Pipe Straight Insulation – Sweat Wrap	Main - Kitchen	20% Chrysotile	Non-Friable	Good	None
PS-3-B			Not Analyzed			
PS-3-C						
CT-2-A	Ceiling Tile – 2’x4’ – Deep Markings	Main - Library	2% Chrysotile	Non-Friable	Good	24
CT-2-B			Not Analyzed			
CT-2-C						
CT-3-A	Ceiling Tile –	Main -	2% Chrysotile	Non-	Good	25



Sample ID	Material	Location	% Asbestos Concentration	Friability	Condition	Photo #
CT-3-B	2’x4’ – Light Markings	Library	Not Analyzed	Friable		
CT-3-C						
MS-1-A	Mastic – Glue on Tiles	Main - Library	2% Chrysotile	Non-Friable	Good	26
MS-1-B			Not Analyzed			
MS-1-C						
PL-2-A	Plaster on Concrete	Main – Basement Storage	2% Chrysotile	Non-Friable	Good	27
PL-2-B			Not Analyzed			
PL-2-C						
CT-4-A	Ceiling Tile – 2’x4’	Main – Ground Corridor	None Detected	Non-Friable	Good	28
CT-4-B						
CT-4-C						
PL-3-A	Plaster	Main – Ground Corridor	1% Chrysotile	Non-Friable	Good	29
PL-3-B		Main – 009	Not Analyzed			
PL-3-C		Main – 007				
PL-3-D		Main – 006				
PL-3-E		Main – 005				
PL-3-F		Main – 014				
PL-3-G		Main – 011				
CT-5-A	Ceiling Tile – 1’x1’	Main – 009	None Detected	Non-Friable	Good	30
CT-5-B						
CT-5-C						
VT-6-A	Vinyl Floor Tile – Grey 9”x9”	Main – 009	5% Chrysotile (Mastic)	Non-Friable	Good	31
VT-6-B			Not Analyzed			
VT-6-C						
VT-7-A	Vinyl Floor Tile – Grey 1’x1’	Main – 009	None Detected	Non-Friable	Good	None
VT-7-B						
VT-7-C						
VT-8-A	Vinyl Floor Tile – Grey/Blue 1’x1’	Main – 008	5% Chrysotile (Mastic)	Non-Friable	Good	33
VT-8-B			Not Analyzed			
VT-8-C						
VT-9-A	Vinyl Floor Tile	Main – 007	5% Chrysotile	Non-	Good	34



Sample ID	Material	Location	% Asbestos Concentration	Friability	Condition	Photo #
VT-9-B	– Grey Patterned		Not Analyzed	Friable		
VT-9-C						
VT-10-A	Vinyl Floor Tile – White Patterned 1’x1’	Main – 007	5% Chrysotile (Mastic)	Non-Friable	Good	35
VT-10-B			Not Analyzed			
VT-10-C						
VT-11-A	Vinyl Floor Tile – White 9’x9”	Main – 007	None Detected	Non-Friable	Good	36
VT-11-B			5% Chrysotile (Mastic)			
VT-11-C			Not Analyzed			
MB-1-A	Thermal Insulation	Main – Boiler	10% Amosite 5% Chrysotile	Friable	Good	37
MB-1-B			Not Analyzed			
MB-1-C						
CT-6-A	Ceiling Tile – 1’x1’	Main – 007	None Detected	Non-Friable	Good	38
CT-6-B						
CT-6-C						
CT-7-A	Ceiling Tile – 1’x1’	Main – 006	2% Amosite 3% Chrysotile	Non-Friable	Good	39
CT-7-B			Not Analyzed			
CT-7-C						
VT-12-A	Vinyl Floor Tile – Beige 1’x1’	Main – 006	3% Chrysotile	Non-Friable	Good	40
VT-12-B			Not Analyzed			
VT-12-C						
VT-13-A	Vinyl Floor Tile – Blue 1’x1’	Main – 005	None Detected	Non-Friable	Good	41
VT-13-B						
VT-13-C						
FP-2-A	Foundation Parging	Main – Exterior	None Detected	Non-Friable	Good	32
FP-2-B						
FP-2-C						

Based on the analytical results the following building materials were reported to contain 0.5% Asbestos or greater and therefore are considered ACM in accordance with O.Reg 278/05:



### **ANNEX BUILDING**

1. **Plaster** – Non-friable asbestos containing plaster is located throughout walls and ceilings at the Site. See Photo 1.
2. **Drywall Joint Compound** – Non-Friable asbestos containing drywall joint compound is located throughout drywall at the Site. Drywall was observed on interior pillars. See Photo 4.
3. **9"x 9" Vinyl Floor Tile** – Approximately 1,220 square feet were observed throughout the Site in the waiting room, storage room, and room 002. See Photo 8.
4. **Black Vinyl Floor Tile** – Approximately 100 square feet were observed throughout the Site in the waiting room, storage room, and room 002. See Photo 9.
5. **Pipe Fitting Parging Insulation** – Approximately 45 fittings insulated with asbestos containing parging were observed in the mechanical room. See Photo 10.
6. **Pipe Straight Insulation, Corrugated Cardboard (Aircell)** – Approximately 10 linear feet of asbestos containing aircell insulation was observed in the mechanical room. See Photo 11.
7. **Pipe Straight Insulation, Sweat Wrap** – Approximately 20 linear feet of asbestos containing sweat wrap insulation was observed in the mechanical room.

### **MAIN BUILDING**

1. **Pipe Straight Insulation, Corrugated Cardboard (Aircell)** – Approximately 490 linear feet of friable asbestos containing aircell insulation was observed throughout the Site in lunch room 018 and adjacent corridor, kitchen, library, 002, lunch room 017, gymnasium, room outside of fan room, boiler room and adjacent rooms, 009, 008, 006, 006A, and 005. See Photo 21.
2. **Pipe Fitting Parging Insulation** – Approximately 95 fittings insulated with friable asbestos containing parging were observed throughout the Site in lunch room 018 and adjacent corridor, kitchen, library, 002, lunch room 017 and adjacent corridor, gymnasium, room outside of fan room, boiler room and adjacent rooms, and 005. See Photo 22.
3. **Pipe Straight Insulation, Sweat Wrap** – Approximately 45 linear feet of non-friable asbestos containing sweat wrap was observed throughout the Site in lunch room 018 and adjacent corridor and, the kitchen.
4. **Ceiling Tile, 2'x 4' Deep Markings** – Approximately 695 square feet of non-friable asbestos containing ceiling tile was observed in the library. See Photo 24.
5. **Ceiling Tile, 2'x 4' Light Markings** – Approximately 695 square feet of non-friable asbestos containing ceiling tile was observed in the library. See Photo 25.
6. **Mastic, Glue-on Ceiling Tile** – Approximately 1400, 2 inch diameter deposits of residual non-friable glue-on ceiling tile mastic is located throughout the library ceiling space. See Photo 26.
7. **Plaster on Concrete** – Approximately 680 square feet of non-friable asbestos containing plaster is located in the basement storage room adjacent to lunch room 018. See Photo 27.



8. **Plaster** – Non-friable asbestos containing plaster is located throughout walls and ceilings at the Site. See Photo 29.
9. **9”x 9” Grey Vinyl Floor Tile Mastic** – Approximately 4,527 square feet of non-friable asbestos containing floor tile mastic is located throughout the Site in rooms 009, 007, 005, 014, 013, 012, 011, and 010. See Photo 31.
10. **1’x 1’ Grey/Blue Vinyl Floor Tile Mastic** – Approximately 621 square feet of non-friable asbestos containing floor tile mastic is located in room 008. See Photo 33.
11. **Grey Patterned Vinyl Floor Tile Mastic** – Approximately 110 square feet of non-friable asbestos containing floor tile mastic is located in room 007. See Photo 34.
12. **1’x 1’ White Vinyl Floor Tile Mastic** – Approximately 80 square feet of non-friable asbestos containing floor tile mastic is located in room 007. See Photo 35.
13. **9”x 9” White Vinyl Floor Tile Mastic** – Approximately 15 square feet of non-friable asbestos containing floor tile mastic is located in room 007. See Photo 36.
14. **Boiler Insulation, Mag Block** – Approximately 30 square feet of friable asbestos containing mag block insulation is located on the boiler duct work in the boiler room. See Photo 37.
15. **1’x 1’ Ceiling Tile** – Approximately 210 square feet of non-friable asbestos containing ceiling tile is located in room 006. See Photo 39.
16. **1’x 1’ Beige Vinyl Floor Tile** – Approximately 35 square feet of non-friable asbestos containing floor tile is located throughout the Site in rooms 006 and 007. See Photo 40.

Based on the visual inspection the following potential asbestos containing materials are present at the main building.

1. Roofing materials including asphalt shingles or sheet and felts.
2. Ceiling panels located in the gymnasium.
3. Caulking.
4. Mastic located above glue-on ceiling tiles.
5. Mortars.

Based on the visual inspection potential asbestos containing vermiculite may be present in concrete block walls. This material is one of the more hazardous potential asbestos containing building materials as asbestos fibres are not bound in the material. The insulation should be reviewed under controlled conditions during asbestos abatement.

The aforementioned potential ACMs were observed to be in good condition at the time of the DSS. These materials were not sampled to preserve the integrity of the site or they were inaccessible during the DSS. They should be sampled prior to disturbance or demolition, or may be treated as ACM without further assessment.

This assessment does not account for any potential ACMs that were inaccessible during the DSS. Inaccessible locations of potential ACMs include but are not limited to wall cavities, ceiling cavities, and



materials enclosed by flooring or other materials. Additional assessment of ACMs may be required prior renovations, alterations, or demolition of the site.

## 7.0 LEAD BASED PAINT SURVEY

### 7.1 General

The lead based paint survey was conducted by EHS<sup>p</sup> to satisfy Section 30 of the Occupational Health and Safety Act of Ontario. The Federal Government has been limiting the concentration of lead allowed in manufactured paints since the 1970's. Painted surfaces that were applied prior to the 1980's likely contain elevated concentrations of lead. Exterior painted surfaces applied prior to the 1990's potentially contain elevated concentrations of lead. General industry practice is to categorize any painted surface that contains 0.5% (5000 ppm) or greater concentration of elemental lead as a lead based paint. Paint that contains less than 0.5% lead is considered lead containing.

### 7.2 Findings

EHS<sup>p</sup> personnel completed the site reconnaissance including visual inspection and sampling of potential lead based paints. As part of the lead based paint survey ten representative paint chip samples were collected for lead characterization. The painted surfaces that were sampled included walls, ceiling, flooring, ducting, and other painted surfaces.

Sampled materials were submitted using a chain of custody to Steve Moody Micro Services, of Farmers Branch, Texas. The analytical results are presented in appendix B and are summarized in the following table:

**Table 2: Summary of Laboratory Analytical Results – Lead Paint**

Sample ID	Colour (Painted Surface)	Location	Lead Concentration % (ppm)	Condition	Photo #
LBP-A	Beige Wall Paint	Annex – Room 004A	0.1% (1,128 ppm)	Good	43
LBP-B	White Ceiling Paint	Annex – Waiting Room	0.1% (1,300 ppm)	Good	44
LBP-C	Grey Floor Paint	Annex – Mechanical Room	0.1% (1,149 ppm)	Good	45
LBP-D	White Wall Paint	Annex – Room 004	0.02% (153.7 ppm)	Good	46
LBP-E	Beige Wall Paint	Main – Kitchen	0.28% (2,814 ppm)	Good	47
LBP-F	Yellow Duct Paint	Main – Lunch 017	0.24% (2,465 ppm)	Good	None
LBP-G	Grey Floor Paint	Main – Boiler Room	0.2% (1,955 ppm)	Good	49
LBP-H	Yellow Window Frame Paint	Main – Room 006	0.1% (1,261 ppm)	Good	50
LBP-I	Blue Ladder Paint	Main – Room 014	0.14% (1,444 ppm)	Good	51
LBP-J	Yellow Brick Paint	Main – Room 004	0.1% (1,243 ppm)	Good	52



Based on the analytical results lead containing paint was identified throughout the site. Please note that lead is likely present in the solder of copper pipes and this material was not sampled.

## **8.0 HAZARDOUS MATERIALS SURVEY**

### **8.1 General**

The field survey included the visual identification of materials that are potentially hazardous to site occupants, workers, and others.

The following sections provide an overview of the potential hazardous materials of interest and the potential presence of such substances at the site.

### **8.2 Polychlorinated Biphenyls**

#### **8.2.1 General**

Polychlorinated Biphenyls (PCBs) are a group of man-made organic compounds made up of a specific structure that includes two benzene rings or phenyl functional groups. Commercial production began in the 1920's and they were used primarily as coolants and insulating fluids used widely in transformers and capacitors. The removal and disposal of PCBs is governed by Federal Regulation SOR/2008-273, PCBs Regulations, made under the Canadian Environmental Protection Act.

PCBs interfere with hormone production in people causing toxic and mutagenic affects. PCBs are a persistent pollutant and must not be released into the environment.

#### **8.2.2 Findings**

During the DSS a representative amount of light ballasts were reviewed. PCB containing light ballasts were not identified however there is still the potential that PCB containing light ballasts are present at the Site.

### **8.3 Mould**

#### **8.3.1 General**

Mould is a term that generally refers to a specific group of fungi. Mould growth on building materials can impact air quality because toxigenic or allergenic constituents can be dispersed in the air and may be inhaled. Reactions to mould vary depending on physical health, genetics, and age. Common symptoms of mould exposure include cough, congestion, eye irritation, runny nose, headache, fatigue, and vexation of asthma. In some cases, mould is known or suspected to cause serious illness.

#### **8.3.2 Findings**

Based on EHS<sup>p</sup> observations visible potential mould growth was observed on pipe insulation located in the Main building in the room just outside the fan room. Evidence of moisture infiltration through building materials including the presence of residual salts on walls, carpet staining, and significant paint delamination were observed throughout the basement at the Site. This may be an indication that moisture proofing elements of the main building foundation have degraded. The areas that are most affected by water infiltration include the library, garbage room, and shower room adjacent to the boiler room. Additionally water staining was observed on the gymnasium ceiling and the ceiling in room 007. This



moisture staining may indicate that roofing systems at the Site have degraded. Wetting of building materials is the primary cause of mould contamination in buildings. The conditions at the Site are potentially hazardous to occupants, workers, or others at the Site.

## **9.0 CONCLUSIONS AND RECOMMENDATIONS**

The following recommendations are based on the DSS conducted by EHS<sup>p</sup> at 2720 Richmond Road, Ottawa, Ontario on April 4, 2012:

### **General**

The Occupational Health and Safety Act require building owners and their agents to notify all employees, and contractors of the presence of designated substances at a project site. Additional assessment of designated substances may be required prior to renovations, alterations, or demolition of the site.

### **Asbestos**

The following recommendations are based on the requirements of Ontario Regulation 278/05 – Regulation Respecting Asbestos on Construction Projects and in Buildings and Repair Operations:

1. Provide written notice to any occupant detailing ACM discovered at the Site.
2. Provide a copy of this report or applicable portions of this report to maintenance personnel or contractors that work in close vicinity to ACM.
3. The building owner or their agents must inspect the condition of ACM at reasonable intervals. A reasonable interval is not defined by the regulation.
4. This record must be updated when there are any changes to the ACM inventory or at least once every 12 months if there are no changes.
5. Asbestos waste generated by asbestos abatement activities must be packaged, labelled, and disposed of in accordance with Ontario Regulation 347/90 (as amended).
6. Potential asbestos containing concrete block insulation should be inspected during asbestos abatement activities within the Annex Building at the Site.
7. All asbestos containing materials must be removed from the Site to the highest extent practicable prior to demolition.
8. The building owner must institute and maintain a training program for the instruction of every worker employed who is likely to work in close proximity and may disturb ACM. The minimum requirements for this training program include the following:
  - Hazards of Asbestos Exposure;
  - Use, care, and disposal of protective equipment and clothing to be used and personal hygiene; and
  - Work practices and procedures to be used with ACM.



## **Benzene**

Excessive heat must not be used on wire coatings, plastic materials, or PVC as heat may release benzene. If these practices cannot be avoided then implement control measures appropriate for the control of benzene prescribed in Ontario Regulation 490/09 – Designated Substances. This regulation is exempt from construction projects but provides useful guidance on personal protection when a specific regulation or guideline for a specific designated substance is not available for the construction industry.

## **Lead**

Measures prescribed in the Ministry of Labour's Guideline titled "Lead on Construction Projects" should be followed during the disturbance of any painted surface.

## **Mercury**

Mercury containing fluorescent light tubes must be carefully removed and containerized for disposal in accordance with Ontario Regulation 347/09 (as amended) when removed.

## **Mould**

Investigate and correct moisture issues at the Site and remove any mould impacted building materials and debris in accordance with the "Mould Guidelines for the Canadian Construction Industry" (Canadian Construction Association, Document CCA 82 as amended). Ventilation duct cleaning should be included in the scope of work for mould remediation. Retain a building science professional to investigate the integrity of moisture proofing elements of the main building.

## **Polychlorinated Biphenyls (PCBs)**

Any PCB containing ballasts discovered at the Site should be separated from the light fixtures and containerized when removed in accordance with Federal Regulation SOR/2008-273 – PCB Regulations.

## **Silica**

Measures prescribed in the Ministry of Labour's Guideline titled "Silica on Construction Projects", should be followed during the disturbance of any silica containing material

## **Vinyl Chloride**

Excessive heat must not be used on wire coatings, plastic materials, or PVC as heat may release vinyl chloride. If these practices cannot be avoided then implement control measures appropriate for the control of vinyl chloride prescribed in Ontario Regulation 490/09 – Designated Substances. This regulation is exempt from construction projects but provides useful guidance on protection when a specific regulation or guideline for a specific designated substance is not available.



## **10.0 LIMITATIONS**

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Photolog**

Designated Substances Survey  
2720 Richmond Road  
Ottawa, ON  
EHS<sup>P</sup> Project No.: 04-0068-12-001









**Photo 1:**

Representative view of asbestos containing plaster, Annex Building, Room 004, Sample Set PL-1-X



**Photo 2:**

View of Representative Vinyl Floor Tile, 1'x 1' Grey, Annex Building, Room 001, Sample Set: VT-1-X.






**Photo 3:** View of Representative Vinyl Floor Tile, 1'x 1' White, Annex Building, Room 001, Sample Set: VT-1-X.



**Photo 4:** View of Representative Cove Base, Annex Building, Room 001, Sample Set: CB-1-X.





**Photo 5:**

View of Representative 1'X 1' Ceiling Tile, Annex Building, Room 001, Sample Set: CT-1-X.



**Photo 6:**

View of Representative Drywall with Asbestos Containing Drywall Joint Compound, Annex Building, Room 001, Sample Set: DC-1-X. Pillars within the Annex Building are constructed with drywall.





**Photo 7:**

View of Representative Concrete Block Mortar, Annex Building, Teachers Lounge, Sample Set: MT-1-X.



**Photo 8:**

View of Representative Asbestos Containing 9"x 9" Vinyl Floor Tile, Annex Building, Waiting Room, Sample Set: VT-3-X.





**Photo 9:**

View of Representative Asbestos Containing Black Vinyl Floor Tile, Annex Building, Waiting Room, Sample Set: VT-4-X.



**Photo 10:**

View of Representative Pipe Fitting Parging Insulation, Annex Building, Mechanical Room, Sample Set: PR-1-X.





**Photo 11:**

View of Representative Asbestos Containing Pipe Straight Corrugated Cardboard Insulation, Annex Building, Mechanical Room, Sample Set: PS-1-X.

No Photo Available

**Photo 12:**

Asbestos Containing Pipe Straight Sweat Wrap Insulation, Annex Building, Mechanical Room, Sample Set: TP-1-X.





**Photo 13:**

View of Representative Vinyl Floor Tile, Annex Building, Room 002, Sample Set: VT-5-X.




**Photo 14:**

View of Representative Black Caulking, Annex Building, Exterior, Sample Set: CA-1-X.





**Photo 15:** View of Representative Annex Building Main Roof (Core Sampled), Annex Building, Exterior, Sample Set: RC-X.



**Photo 16:** View of Representative Asphalt Shingles, Annex Building, Entrance Roof, Sample Set: AS-X.





**Photo 17:**

View of Representative Beige Caulking, Annex Building, Exterior, Sample Set: CA-2-X.




**Photo 18:**

View of Representative Trowelled Cementitious Material, Annex Building, Exterior, Sample Set: TC-X.






**Photo 19:** View of Representative Foundation Parging, Annex Building, Exterior, Sample Set: FP-1-X.



**Photo 20:** View of Representative Brick Mortar, Annex Building, Exterior, Sample Set: MR-1-X.





**Photo 21:**

View of Representative Asbestos Containing Pipe Straight Corrugated Cardboard Insulation, Main Building, Lunch Room 018, Sample Set: PS-2-X.



**Photo 22:**

View of Representative Pipe Fitting Parging Insulation, Main Building, Lunch Room 018, Sample Set: PR-2-X.



No Photo Available

<b>Photo 23:</b>	Asbestos Containing Pipe Straight Sweat Wrap Insulation, Main Building, Mechanical Room, Sample Set: PS-3-X.
------------------	--



<b>Photo 24:</b>	View of Representative Asbestos Containing Ceiling Tile, 2'x 4'Deep Markings, Main Building, Library, Sample Set: CT-2-X.
------------------	---





**Photo 25:**

View of Representative Asbestos Containing Ceiling Tile, 2'x 4' Light Markings, Main Building, Library, Sample Set: CT-3-X.



**Photo 26:**

View of Representative Asbestos Containing Ceiling Tile Mastic, Main Building, Library Ceiling Space, Sample Set: MS-1-X.





**Photo 27:** View of Representative Asbestos Containing Plaster located on Concrete, Main Building, Storage Room, Sample Set: PL-2-X.




**Photo 28:** View of Representative Ceiling Tile, 2'x 4', Main Building, Ground Floor Corridor, Sample Set: CT-4-X.





**Photo 29:** View of Representative Asbestos Containing Plaster, Main Building, Ground Floor Corridor, Sample Set: PL-3-X.



**Photo 30:** View of Representative Ceiling Tile, 1'x 1', Main Building, Room 009, Sample Set: CT-5-X.





**Photo 31:**


View of Representative 9"x 9" Grey Vinyl Floor Tile with Asbestos Containing Mastic, Main Building, Room 009, Sample Set: VT-6-X.

No Photo Available


**Photo 32:**

1'X 1' Grey Vinyl Floor Tile, Main Building, Room 009, Sample Set: VT-7-X.





**Photo 33:** View of Representative 1' X 1' Grey/Blue Vinyl Floor Tile with Asbestos Containing Mastic, Main Building, Room 008, Sample Set: VT-8-X.



**Photo 34:** View of Representative 1' X 1' Grey Patterned Vinyl Floor Tile with Asbestos Containing Mastic, Main Building, Room 007, Sample Set: VT-9-X.






**Photo 35:** View of Representative 1' X 1' White Patterned Vinyl Floor Tile with Asbestos Containing Mastic, Main Building, Room 007, Sample Set: VT-10-X.



**Photo 36:** View of Representative 9" x 9" White Vinyl Floor Tile with Asbestos Containing Mastic, Main Building, Room 007, Sample Set: VT-11-X.





**Photo 37:** View of Representative Asbestos Containing Thermal Insulation (Mag Block), Main Building, Boiler Room, Sample Set: MB-1-X.



**Photo 38:** View of Representative 1'x 1' Ceiling Tile, Main Building, Room 007, Sample Set: CT-6-X.





**Photo 39:** View of Representative Asbestos Containing 1'x 1' Ceiling Tile, Main Building, Room 006, Sample Set: CT-6-X.



**Photo 40:** View of Representative Asbestos Containing 1'x 1' Beige Vinyl Floor Tile, Main Building, Room 006, Sample Set: VT-12-X.





**Photo 41:**

View of Representative 1'x 1' Blue Vinyl Floor Tile, Main Building, Room 005, Sample Set: VT-13-X.



**Photo 42:**

View of Representative Foundation Parging, Main Building, Exterior, Sample Set: FP-2-X.





**Photo 43:** View of Representative Lead Containing Beige Wall Paint, Annex Building, Room 004A, Sample: LBP-A.



**Photo 44:** View of Representative Lead Containing White Ceiling Paint, Annex Building, Waiting Room, Sample: LBP-B.





**Photo 45:** View of Representative Lead Containing Grey Floor Paint, Annex Building, Mechanical Room, Sample: LBP-C.



**Photo 46:** View of Representative Lead Containing White Wall Paint, Annex Building, Room 004, Sample: LBP-D.





**Photo 47:** View of Representative Lead Containing Beige Wall Paint, Main Building, Kitchen, Sample: LBP-E.

No Photo Available

**Photo 48:** Lead Containing Yellow Duct Paint, Main Building, Lunch Room 017, Sample: LBP-F.





**Photo 49:** View of Representative Lead Containing Grey Floor Paint, Annex Building, Room 004, Sample: LBP-G.



**Photo 50:** View of Representative Lead Containing Yellow Window Frame Paint, Main Building, Room 006, Sample: LBP-H.





**Photo 51:** View of Representative Lead Containing Blue Ladder Paint, Main Building, Room 014, Sample: LBP-I.



**Photo 52:** View of Representative Lead Containing Yellow Wall Paint, Main Building, Room 004, Sample: LBP-J.





**Photo 53:** View of Representative Potential Asbestos Containing Ceiling Mesh-like Panels, Main Building, Gymnasium. Inaccessible during initial assessment.




**Photo 54:** View of Moisture Impacted Carpet, Evidence of Moisture Infiltration, Main Building, Library.





**Photo 55:** View of Moisture Impacted Wall, Evidence of Moisture Infiltration, Main Building, Library.



**Photo 56:** View of Moisture Impacted Wall, Evidence of Moisture Infiltration, Residual Salts Transported by Moisture Through Porous Materials, Main Building, Garbage Room.





**Photo 57:**

View of Moisture Impacted Wall, Adjacent Crawlspace is filled with Water, Main Building, Boiler Room.







## **Appendix B**

### **Analytical Results**

Designated Substances Survey  
2720 Richmond Road  
Ottawa, ON  
EHS<sup>p</sup> Project No.: 04-0068-12-001







## PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PL-1-A	Plaster, Annex, 004A	None Detected - Base Plaster None Detected - Top Plaster
PL-1-B	Plaster, Annex, 001	2% Chrysotile - Base Plaster None Detected - Top Plaster
PL-1-C	Plaster, Annex, Teaching Lounge	Not Analyzed - Positive Stop
PL-1-D	Plaster, Annex, Waiting	Not Analyzed - Positive Stop
PL-1-E	Plaster, Annex, 002	Not Analyzed - Positive Stop
PL-1-F	Plaster, Annex, 003	Not Analyzed - Positive Stop
PL-1-G	Plaster, Annex, 004	Not Analyzed - Positive Stop
VT-1-A	1' x 1' Vinyl Floor Tile (Grey), Annex, 001	None Detected - Floor Tile None Detected - Yellow Mastic None Detected - Black Mastic
VT-1-B	1' x 1' Vinyl Floor Tile (Grey), Annex, 001	None Detected - Floor Tile None Detected - Yellow Mastic None Detected - Black Mastic
VT-1-C	1' x 1' Vinyl Floor Tile (Grey), Annex, 001	None Detected - Floor Tile None Detected - Yellow Mastic None Detected - Black Mastic
VT-2-A	1' x 1' Vinyl Floor Tile (White), Annex, 001	None Detected - Floor Tile None Detected - Black Mastic
VT-2-B	1' x 1' Vinyl Floor Tile (White), Annex, 001	None Detected - Floor Tile None Detected - Black Mastic
VT-2-C	1' x 1' Vinyl Floor Tile (White), Annex, 001	None Detected - Floor Tile None Detected - Black Mastic
CB-A	Cove Base, Annex, 001	None Detected - Cove Base None Detected - Yellow Mastic
CB-B	Cove Base, Annex, 001	None Detected - Cove Base None Detected - Yellow Mastic



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 2 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
CB-C	Cove Base, Annex, 001	None Detected - Cove Base None Detected - Yellow Mastic
CT-1-A	1' x 1' Ceiling Tile, Annex, 001	None Detected - Acoustic Tile None Detected - Brown Mastic
CT-1-B	1' x 1' Ceiling Tile, Annex, 001	None Detected - Acoustic Tile None Detected - Brown Mastic
CT-1-C	1' x 1' Ceiling Tile, Annex, 001	None Detected - Acoustic Tile None Detected - Brown Mastic
DC-1-A	Drywall Joint Compound, Annex, 001	2% Chrysotile - Joint Compound
DC-1-B	Drywall Joint Compound, Annex, Waiting	Not Analyzed - Positive Stop
DC-1-C	Drywall Joint Compound, Annex, Girls' Washroom	Not Analyzed - Positive Stop
DC-1-D	Drywall Joint Compound, Annex, 004	Not Analyzed - Positive Stop
DC-1-E	Drywall Joint Compound, Annex, 004	Not Analyzed - Positive Stop
MT-1-A	Mortar, Concrete Block, Annex, Teachers' Lounge	None Detected - Mortar
MT-1-B	Mortar, Concrete Block, Annex, Teachers' Lounge	None Detected - Mortar
MT-1-C	Mortar, Concrete Block, Annex, Teachers' Lounge	None Detected - Mortar
VT-3-A	9" x 9" Vinyl Floor Tile (Yellow), Annex, Waiting	10% Chrysotile - Floor Tile No Mastic
VT-3-B	9" x 9" Vinyl Floor Tile (Yellow), Annex, Waiting	Not Analyzed - Positive Stop
VT-3-C	9" x 9" Vinyl Floor Tile (Yellow), Annex, Waiting	Not Analyzed - Positive Stop
VT-4-A	Vinyl Floor Tile (Black), Annex, Waiting	10% Chrysotile - Floor Tile
VT-4-B	Vinyl Floor Tile (Black), Annex, Waiting	Not Analyzed - Positive Stop
VT-4-C	Vinyl Floor Tile (Black), Annex, Waiting	Not Analyzed - Positive Stop
PR-1-A	Fitting Insulation, Parging, Annex, Mechanical Room	65% Chrysotile - Thermal Insulation



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 3 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PR-1-B	Fitting Insulation, Parging, Annex, Mechanical Room	Not Analyzed - Positive Stop
PR-1-C	Fitting Insulation, Parging, Annex, Mechanical Room	Not Analyzed - Positive Stop
PS-1-A	Pipe Straight Insulation, Corrugated Cardboard, Annex, Mechanical Room	90% Chrysotile - Thermal Insulation
PS-1-B	Pipe Straight Insulation, Corrugated Cardboard, Annex, Mechanical Room	Not Analyzed - Positive Stop
PS1-C	Pipe Straight Insulation, Corrugated Cardboard, Annex, Mechanical Room	Not Analyzed - Positive Stop
TP-A	Pipe Straight Insulation, Sweat Wrap Tar Paper, Annex, Mechanical Room	5% Chrysotile - Black Wrap None Detected - Tan Wrap
TP-B	Pipe Straight Insulation, Sweat Wrap Tar Paper, Annex, Mechanical Room	Not Analyzed - Positive Stop
TP-C	Pipe Straight Insulation, Sweat Wrap Tar Paper, Annex, Mechanical Room	Not Analyzed - Positive Stop
VT-5-A	1' x 1' Vinyl Floor Tile (Blue), Annex, 002	None Detected - Floor Tile None Detected - Black Mastic
VT-5-B	1' x 1' Vinyl Floor Tile (Blue), Annex, 002	None Detected - Floor Tile None Detected - Black Mastic
VT-5-C	1' x 1' Vinyl Floor Tile (Blue), Annex, 002	None Detected - Floor Tile None Detected - Black Mastic
CA-1-A	Caulking (Black), Annex, Roof	None Detected - Caulking
CA-1-B	Caulking (Black), Annex, Roof	None Detected - Caulking
CA-1-C	Caulking (Black), Annex, Roof	None Detected - Caulking
RC-A	Roofing Core Sample, Annex, Main Roof	None Detected - Roof Membrane None Detected - Roofing Tars None Detected - Underlayment



## PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 4 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
RC-B	Roofing Core Sample, Annex, Main Roof	None Detected - Roof Membrane None Detected - Roofing Tars
RC-C	Roofing Core Sample, Annex, Main Roof	None Detected - Roof Membrane None Detected - Roofing Tars
AS-A	Asphalt Shingle, Annex, Entrance Roof	None Detected - Roofing Shingle
AS-B	Asphalt Shingle, Annex, Entrance Roof	None Detected - Roofing Shingle
AS-C	Asphalt Shingle, Annex, Entrance Roof	None Detected - Roofing Shingle
CA-2-A	Caulking (Beige), Annex, Exterior	None Detected - Caulking
CA-2-B	Caulking (Beige), Annex, Exterior	None Detected - Caulking
CA-2-C	Caulking (Beige), Annex, Exterior	None Detected - Caulking
TC-A	Troweled Cementitious Material, Annex, Exterior Windows	None Detected - Cementitious Material
TC-B	Troweled Cementitious Material, Annex, Exterior Windows	None Detected - Cementitious Material
TC-C	Troweled Cementitious Material, Annex, Exterior Windows	None Detected - Cementitious Material
FP-1-A	Foundation Parging, Annex, Exterior	None Detected - Parging
FP-1-B	Foundation Parging, Annex, Exterior	None Detected - Parging
FP-1-C	Foundation Parging, Annex, Exterior	None Detected - Parging
PS-2-A	Pipe Straight Insulation, Corrugated Cardboard, Main, Lunch Room 018	90% Chrysotile - Thermal Insulation None Detected - Cotton Wrap
PS-2-B	Pipe Straight Insulation, Corrugated Cardboard, Main, Lunch Room 018	Not Analyzed - Positive Stop
PS-2-C	Pipe Straight Insulation, Corrugated Cardboard, Main, Lunch Room 018	Not Analyzed - Positive Stop
PR-2-A	Pipe Fitting Insulation, Parging, Main, Lunch Room 018	65% Chrysotile - Thermal Insulation
PR-2-B	Pipe Fitting Insulation, Parging, Main, Kitchen	Not Analyzed - Positive Stop



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 5 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PR-2-C	Pipe Fitting Insulation, Parging, Main, Boiler Room	Not Analyzed - Positive Stop
PS-3-A	Pipe Straight Insulation, Sweat Wrap, Main, Kitchen	None Detected - Tan Insulation 20% Chrysotile - White Insulation None Detected - Cotton Wrap
PS-3-B	Pipe Straight Insulation, Sweat Wrap, Main, Kitchen	Not Analyzed - Positive Stop
PS-3-C	Pipe Straight Insulation, Sweat Wrap, Main, Kitchen	Not Analyzed - Positive Stop
CT-2-A	2' x 4' Ceiling Tile (Deep Markings), Main, Library	2% Chrysotile - Acoustic Tile
CT-2-B	2' x 4' Ceiling Tile (Deep Markings), Main, Library	Not Analyzed - Positive Stop
CT-2-C	2' x 4' Ceiling Tile (Deep Markings), Main, Library	Not Analyzed - Positive Stop
CT-3-A	2' x 4' Ceiling Tile (Light Markings), Main, Library	2% Chrysotile - Acoustic Tile
CT-3-B	2' x 4' Ceiling Tile (Light Markings), Main, Library	Not Analyzed - Positive Stop
CT-3-C	2' x 4' Ceiling Tile (Light Markings), Main, Library	Not Analyzed - Positive Stop
MS-1-A	Mastic, Glue on Tiles, Main, Library	2% Chrysotile - Brown Mastic
MS-1-B	Mastic, Glue on Tiles, Main, Library	Not Analyzed - Positive Stop
MS-1-C	Mastic, Glue on Tiles, Main, Library	Not Analyzed - Positive Stop
PL-2-A	Plaster on Concrete, Main, Basement Storage	None Detected - Base Plaster 2% Chrysotile - Top Plaster
PL-2-B	Plaster on Concrete, Main, Basement Storage	Not Analyzed - Positive Stop
PL-2-C	Plaster on Concrete, Main, Basement Storage	Not Analyzed - Positive Stop
CT-4-A	2' x 4' Ceiling Tile, Main, Ground Corridor	None Detected - Acoustic Tile
CT-4-B	2' x 4' Ceiling Tile, Main, Ground Corridor	None Detected - Acoustic Tile
CT-4-C	2' x 4' Ceiling Tile, Main, Ground Corridor	None Detected - Acoustic Tile



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 6 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PL-3-A	Plaster, Main, Ground Corridor	None Detected - Bottom Plaster 1% Chrysotile - Top Plaster
PL-3-B	Plaster, Main, 009	Not Analyzed - Positive Stop
PL-3-C	Plaster, Main, 007	Not Analyzed - Positive Stop
PL-3-D	Plaster, Main, 006	Not Analyzed - Positive Stop
PL-3-E	Plaster, Main, 005	Not Analyzed - Positive Stop
PL-3-F	Plaster, Main, 014	Not Analyzed - Positive Stop
PL-3-G	Plaster, Main, 011	Not Analyzed - Positive Stop
CT-5-A	1' x 1' Ceiling Tile, Main, 009	None Detected - Acoustic Tile
CT-5-B	1' x 1' Ceiling Tile, Main, 009	None Detected - Acoustic Tile
CT-5-C	1' x 1' Ceiling Tile, Main, 009	None Detected - Acoustic Tile
VT-6-A	9" x 9" Vinyl Floor Tile (Grey), Main, 009	None Detected - Floor Tile None Detected - Yellow Mastic 5% Chrysotile - Black Mastic
VT-6-B	9" x 9" Vinyl Floor Tile (Grey), Main, 009	Not Analyzed - Positive Stop
VT-6-C	9" x 9" Vinyl Floor Tile (Grey), Main, 009	Not Analyzed - Positive Stop
VT-7-A	1' x 1' Vinyl Floor Tile (Grey), Main, 009	None Detected - Floor Tile None Detected - Yellow Mastic
VT-7-B	1' x 1' Vinyl Floor Tile (Grey), Main, 009	None Detected - Floor Tile None Detected - Yellow Mastic
VT-7-C	1' x 1' Vinyl Floor Tile (Grey), Main, 009	None Detected - Floor Tile None Detected - Yellow Mastic
VT-8-A	1' x 1' Vinyl Floor Tile (Grey / Blue), Main, 008	None Detected - Floor Tile None Detected - Black Mastic 1 5% Chrysotile - Black Mastic 2



## PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client :	EHS Partnerships Ltd. - Ottawa, ON	Lab Job No. : 12B-04117	003
Project :	2720 Richmond Road	Report Date : 04/16/2012	
Project # :	04-0068-12-001	Sample Date : 04/04/2012	
Identification :	Asbestos, Bulk Sample Analysis		
Test Method :	Polarized Light Microscopy / Dispersion Staining (PLM/DS) EPA Method 600 / R-93 / 116		

Page 7 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
VT-8-B	1' x 1' Vinyl Floor Tile (Grey / Blue), Main, 008	Not Analyzed - Positive Stop
VT-8-C	1' x 1' Vinyl Floor Tile (Grey / Blue), Main, 008	Not Analyzed - Positive Stop
VT-9-A	Vinyl Floor Tile (Grey Patterned), Main, 007	None Detected - Floor Tile None Detected - Black Mastic 1 5% Chrysotile - Black Mastic 2
VT-9-B	Vinyl Floor Tile (Grey Patterned), Main, 007	Not Analyzed - Positive Stop
VT-9-C	Vinyl Floor Tile (Grey Patterned), Main, 007	Not Analyzed - Positive Stop
VT-10-A	1' x 1' Vinyl Floor Tile (White Patterned), Main, 007	None Detected - Floor Tile None Detected - Black Mastic 1 5% Chrysotile - Black Mastic 2
VT-10-B	1' x 1' Vinyl Floor Tile (White Patterned), Main, 007	Not Analyzed - Positive Stop
VT-10-C	1' x 1' Vinyl Floor Tile (White Patterned), Main, 007	Not Analyzed - Positive Stop
VT-11-A	9" x 9" Vinyl Floor Tile (White), Main, 007	None Detected - Floor Tile No Mastic
VT-11-B	9" x 9" Vinyl Floor Tile (White), Main, 007	None Detected - Floor Tile 5% Chrysotile - Black Mastic
VT-11-C	9" x 9" Vinyl Floor Tile (White), Main, 007	Not Analyzed - Positive Stop
MB-1-A	Thermal Insulation, Main, Boiler	10% Amosite - Thermal Insulation 5% Chrysotile - Thermal Insulation
MB-1-B	Thermal Insulation, Main, Boiler	Not Analyzed - Positive Stop
MB-1-C	Thermal Insulation, Main, Boiler	Not Analyzed - Positive Stop
CT-6-A	1' x 1' Ceiling Tile, Main, 007	None Detected - Acoustic Tile
CT-6-B	1' x 1' Ceiling Tile, Main, 007	None Detected - Acoustic Tile
CT-6-C	1' x 1' Ceiling Tile, Main, 007	None Detected - Acoustic Tile



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001 Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 8 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
CT-7-A	1' x 1' Ceiling Tile, Main, 006	3% Chrysotile - Acoustic Tile 2% Amosite - Acoustic Tile
CT-7-B	1' x 1' Ceiling Tile, Main, 006	Not Analyzed - Positive Stop
CT-7-C	1' x 1' Ceiling Tile, Main, 006	Not Analyzed - Positive Stop
VT-12-A	1' x 1' Vinyl Floor Tile (Beige), Main, 006	3% Chrysotile - Floor Tile None Detected - Black Mastic
VT-12-B	1' x 1' Vinyl Floor Tile (Beige), Main, 006	Not Analyzed - Positive Stop
VT-12-C	1' x 1' Vinyl Floor Tile (Beige), Main, 006	Not Analyzed - Positive Stop
VT-13-A	1' x 1' Vinyl Floor Tile (Blue), Main, 006	None Detected - Floor Tile None Detected - Yellow Mastic
VT-13-B	1' x 1' Vinyl Floor Tile (Blue), Main, 006	None Detected - Floor Tile No Mastic
VT-13-C	1' x 1' Vinyl Floor Tile (Blue), Main, 006	None Detected - Floor Tile Insufficient Mastic
FP-2-A	Foundation Parging, Main, Exterior	None Detected - Parging
FP-2-B	Foundation Parging, Main, Exterior	None Detected - Parging
FP-2-C	Foundation Parging, Main, Exterior	None Detected - Parging
MR-1-A	Brick Mortar, Annex, Exterior	None Detected - Mortar
MR-1-B	Brick Mortar, Annex, Exterior	None Detected - Mortar
MR-1-C	Brick Mortar, Annex, Exterior	None Detected - Mortar



## PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab No. 102056

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 12B-04117

003

Project : 2720 Richmond Road

Report Date : 04/16/2012

Project # : 04-0068-12-001

Sample Date : 04/04/2012

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)

EPA Method 600 / R-93 / 116

Page 9 of 9

On 4/6/2012, one hundred thirty six (136) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. Results may not be reproduced except in full. This test report relates only to the samples tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056.



Analyst(s): Bruce Crabb, Heather Deines, Shaun Wilkerson

Lab Manager : Bruce Crabb

Approved Signatory :

A handwritten signature in black ink, appearing to read "Bruce Crabb", written over a horizontal line.

Lab Director : Steve Moody

Approved Signatory :

A handwritten signature in black ink, appearing to read "Steve Moody", written over a horizontal line.

Thank you for choosing Steve Moody Micro Services









June 11, 2014

EHS<sup>P</sup> Project No.: 04-0068-14-003

Mr. Bernard Benoit  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent. Unit B4  
Ottawa, Ontario, K1B 5N1  
E-mail: [Bernard.Benoit@bbpm.ca](mailto:Bernard.Benoit@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL HAZARDOUS SUBSTANCES ASSESSMENT  
2720 RICHMOND ROAD, MAIN BUILDING  
OTTAWA, ONTARIO**

Dear Mr. Benoit,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Inc. (BBPM) to provide project specific sampling of potential asbestos and PCB containing materials present in the main building located at 2720 Richmond Road, Ottawa, ON (Site). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) and Federal Regulation SOR/2008-273, PCBs Regulations, made under the Canadian Environmental Protection Act.

This report presents additional testing required to carry out renovations of the Site. The findings in this report must be used in conjunction with the initial Site Designated Substances Survey:

- Centre Multiservices Francophone de l'Ouest d'Ottawa, Designated Substances Survey, 2720 Richmond Road, Ottawa, Ontario, April 2012, Prepared by EHS Partnerships Ltd, Ref. No.: 04-0068-12-001.

EHS<sup>P</sup> completed the site reconnaissance on June 4, 2014. Based on the visual inspection EHS<sup>P</sup> collected and subsequently submitted fifteen (15) representative samples from five (5) distinct types of potential asbestos containing materials including ceiling panels and roofing materials. EHS<sup>P</sup> collected and subsequently submitted three (3) representative samples of potential PCB containing roofing materials (roof membranes). All sampled materials were sent to for analysis at 3rd party analytical laboratories.

The samples of the suspect asbestos containing material (ACM) were submitted under chain of custody procedure to Steve Moody Micro Services, of Farmers Branch, Texas for the determination of asbestos content using polarized light microscopy (PLM) analysis in accordance with EPA 600/R-93/116. The sample of potential PCB containing caulking was submitted under chain of custody to EMSL Laboratories, Cinnaminson, New Jersey for analysis of PCB content.



The analytical results are presented in Appendix A and are summarized in the following table:

Sample ID	Description	Test Parameter	Concentration	Comments
CP-XX	Ceiling Panels Gym	Asbestos	None Detected	Not Considered ACM
RM-1-XX	Roofing Materials Second Floor and Gym Membrane	Asbestos	None Detected	Not Considered ACM
RM-2-XX	Roofing Materials East Lower Elevations Sheet over Membrane	Asbestos	None Detected	Not Considered ACM
RM-3-XX	Roofing Materials East Higher Elevation Membrane	Asbestos	None Detected	Not Considered ACM
RM-4-XX	Roofing Materials Inclined Roof Shingle and Underlay	Asbestos	None Detected	Not Considered ACM
RM-1-PCB	Caulking (Grey), Addition, Roof	PCBs	None Detected	Not Considered PCB-containing
RM-2-PCB	Roofing Materials East Lower Elevations Sheet over Membrane	PCBs	None Detected	Not Considered PCB-containing
RM-3-PCB	Roofing Materials East Higher Elevation Membrane	PCBs	None Detected	Not Considered PCB-containing

XX – Indicates multiple representative samples collected in accordance with O. Reg. 278/05.

The analytical results indicate that asbestos was not detected above the Provincial criteria of 0.5% in any of the sampled materials and therefore the materials are not considered ACM in accordance with O. Reg. 278/05.

The analytical results indicate that PCB's were not detected in any of the suspected roofing materials.



We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

**EHS PARTNERSHIPS LTD.**

*per:*

A handwritten signature in dark ink, appearing to read "D. Leclair", written over a horizontal line.

Geoff Leclair, A.Sc.T.  
Project Coordinator



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Results**

Additional Hazardous Substances Assessment

BBPM Inc.

2720 Richmond Road

Ottawa, ON

EHS<sup>P</sup> Project No.: 04-0068-14-003



## PLM Summary Report

*Steve Moody Micro Services, LLC*

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 14B-06858

Project : 2720 Richmond Road, Nepean, Ontario

Report Date : 06/10/2014

Project # : 04-0068-14-003 Sample Date : 06/04/2014

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 2

On 6/5/14, fifteen (15) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
CP-A	Ceiling Panels, Gym	None Detected - Tectum Panel
CP-B	Ceiling Panels, Gym	None Detected - Tectum Panel
CP-C	Ceiling Panels, Gym	None Detected - Tectum Panel
RM-1-A	Roofing Materials, Second Floor and Gym Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-1-B	Roofing Materials, Second Floor and Gym Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-1-C	Roofing Materials, Second Floor and Gym Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-2-A	Roofing Materials, East Lower Elevations, Sheet over Membrane	None Detected - Roof Membrane None Detected - Roof Material None Detected - Roofing Tar None Detected - Underlayment
RM-2-B	Roofing Materials, East Lower Elevations, Sheet over Membrane	None Detected - Roof Membrane None Detected - Roof Material None Detected - Roofing Tar None Detected - Underlayment
RM-2-C	Roofing Materials, East Lower Elevations, Sheet over Membrane	None Detected - Roof Membrane None Detected - Roof Material None Detected - Roofing Tar None Detected - Underlayment
RM-3-A	Roofing Materials, East Higher Elevation, Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-3-B	Roofing Materials, East Higher Elevation, Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-3-C	Roofing Materials, East Higher Elevation, Membrane	None Detected - Roofing Tars None Detected - Roofing Felts
RM-4-A	Roofing Materials, Inclined Roof, Shingle and Underlay	None Detected - Roofing Shingle None Detected - Roofing Felt



## PLM Summary Report

Steve Moody Micro Services, LLC

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 14B-06858

Project : 2720 Richmond Road, Nepean, Ontario

Report Date : 06/10/2014

Project # : 04-0068-14-003 Sample Date : 06/04/2014

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 2 of 2

On 6/5/14, fifteen (15) bulk material samples were submitted by Geoff Leclair of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
RM-4-B	Roofing Materials, Inclined Roof, Shingle and Underlay	None Detected - Roofing Shingle None Detected - Roofing Felt
RM-4-C	Roofing Materials, Inclined Roof, Shingle and Underlay	None Detected - Roofing Shingle None Detected - Roofing Felt

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Steve Moody

Lab Manager : Heather Lopez

Approved Signatory :

Lab Director : Bruce Crabb

Approved Signatory :

Thank you for choosing Steve Moody Micro Services



**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>[Env\\_Chemistry@emsl.com](mailto:Env_Chemistry@emsl.com)

EMSL Order: 011402747

CustomerID: SEAC63

CustomerPO:

ProjectID:

Attn: **Geoff LeClair**  
**EHS Partnerships Ltd.**  
**2 Gurdwara Road**  
**Suite 406**  
**Ottawa, ON K2E 1A2**

Phone: (613) 828-8989  
 Fax: (613) 828-9404  
 Received: 06/05/14 9:40 AM

Project: 04-0068-014-003

**Analytical Results**

**Client Sample Description** RM-01-PCB  
 Roofing Materials, 2nd Level and Gym  
**Collected:** 6/4/2014 10:00:00 AM  
**Lab ID:** 0001

Method	Parameter	Result	RL	Units	Prep Date	Analyst	Analysis Date	Analyst
3550C/8082A	Aroclor-1016	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1221	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1232	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1242	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1248	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1254	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1260	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1262	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1268	ND	0.93	mg/Kg	6/5/2014	RS	6/6/2014	EH

**Client Sample Description** RM-02-PCB  
 Roofing Materials, East Lower  
**Collected:** 6/4/2014 10:00:00 AM  
**Lab ID:** 0002

Method	Parameter	Result	RL	Units	Prep Date	Analyst	Analysis Date	Analyst
3550C/8082A	Aroclor-1016	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1221	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1232	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1242	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1248	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1254	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1260	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1262	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1268	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH

**Client Sample Description** RM-03-PCB  
 Roofing Materials, East Higher  
**Collected:** 6/4/2014 10:00:00 AM  
**Lab ID:** 0003

Method	Parameter	Result	RL	Units	Prep Date	Analyst	Analysis Date	Analyst
3550C/8082A	Aroclor-1016	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1221	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1232	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1242	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1248	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1254	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1260	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1262	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH
3550C/8082A	Aroclor-1268	ND	0.98	mg/Kg	6/5/2014	RS	6/6/2014	EH





## PLM Summary Report

2051 Valley View Lane  
Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 15B-06884

Project : CFMO

Report Date : 06/09/2015

Project # : 04-0068-15-001

Sample Date : 05/07/2015

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 1

On 6/3/2015, twelve (12) bulk material samples were submitted by Trent Windsor of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
CBM-01A	Concrete Block Mortar	None Detected - Mortar
CBM-01B	Concrete Block Mortar	None Detected - Mortar
CBM-01C	Concrete Block Mortar	None Detected - Mortar
INT-BM-01A	Brick Mortar	None Detected - Brick None Detected - Mortar
INT-BM-01B	Brick Mortar	None Detected - Mortar
INT-BM-01C	Brick Mortar	None Detected - Mortar
EXT-BM-01A	Brick Mortar	None Detected - Mortar
EXT-BM-01B	Brick Mortar	None Detected - Mortar
EXT-BM-01C	Brick Mortar	None Detected - Mortar
P-01A	Paper Sheeting	None Detected - Tar Paper
P-01B	Paper Sheeting	None Detected - Tar Paper
P-01C	Paper Sheeting	None Detected - Tar Paper

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Cindy Vongpradith

Lab Manager : Heather Lopez

Approved Signatory : \_\_\_\_\_

Lab Director : Bruce Crabb

Approved Signatory : \_\_\_\_\_

Thank you for choosing Moody Labs



**This Page Left Intentionally Blank**



Moody Labs

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

**PLM Detail Report**  
**Supplement to PLM Summary Report**

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Project : CFMO

Project # : 04-0068-15-001

Lab Job No. : 15B-06884

Report Date : 06/09/2015

Page 1 of 1

Sample Number	Layer	% Of Sample	Components	% of Layer	Analysis Date	Analyst
CBM-01A	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
CBM-01B	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
CBM-01C	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
INT-BM-01A	Brick (Red Brown) Mortar (Grey)	50% 50%	Sintered Clays Aggregate Cement Binders	100% 65% 35%	06/09	CV
INT-BM-01B	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
INT-BM-01C	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
EXT-BM-01A	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
EXT-BM-01B	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
EXT-BM-01C	Mortar (Grey)	100%	Aggregate Cement Binders	65% 35%	06/09	CV
P-01A	Tar Paper (Black)	100%	Cellulose Fibers Tar Binders	85% 15%	06/09	CV
P-01B	Tar Paper (Black)	100%	Cellulose Fibers Tar Binders	85% 15%	06/09	CV
P-01C	Tar Paper (Black)	100%	Cellulose Fibers Tar Binders	85% 15%	06/09	CV





June 10, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent, Unit B4  
Ottawa, Ontario, K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ASBESTOS SAMPLING - FLOOR TOPPING  
2720 RICHMOND ROAD, MAIN BUILDING  
OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Inc. (BBPM) to provide asbestos sampling and analysis of the floor topping observed throughout the main building located at 2720 Richmond Road in Ottawa, Ontario (Site). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the floor topping on each elevation at the Site.

The floor topping was observed and sampled during a pre-construction designated substance survey conducted in May of 2015. The results of the sampling indicated that asbestos was detected in five of seven samples of the floor topping. Asbestos was detected in the Library, and the corridor on the ground floor and second floor of the building. No asbestos was detected in room 17 or 18 in the basement. The results of this sampling can be found in the report titled "Designated Substance Survey Updated for Construction - Main Building Renovation and Rehabilitation, 2720 Richmond Road, Ottawa, Ontario", EHS Partnerships Ltd., May 2015.

The purpose of this sampling event was to determine if the floor topping on the basement level (lunchroom elevation) was indeed non asbestos containing and to determine the asbestos content of the floor topping below the recently removed vinyl flooring on the ground and second floors.

EHS<sup>P</sup> completed the inspection and sampling on May 25, 2015. Based on the visual inspection EHS<sup>P</sup> collected and subsequently submitted seven samples of the floor topping to Steve Moody Micro Services, LLC of Farmers Branch, Texas for analysis via polarized light microscopy (PLM).

The analytical results for the floor topping asbestos sampling are presented in Appendix A and are summarized in the following table:

Sample or Set ID	Location	Asbestos Concentration	Comments
LR/17/18-01A	Lunchroom 017	None Detected	Not Considered ACM
LR/17/18-01B	Lunchroom 018	None Detected	Not Considered ACM
LR/17/18-01A	Gym Storage Room	None Detected	Not Considered ACM



Sample or Set ID	Location	Asbestos Concentration	Comments
005	Room 005 (Ground Floor)	15% Chrysotile	Asbestos Containing Layer Present
006A	Room 006A (Ground Floor)	15% Chrysotile	Asbestos Containing Layer Present
014	Room 014 (Second Floor)	15% Chrysotile	Asbestos Containing Layer Present
012	Room 012 (Second Floor)	15% Chrysotile	Asbestos Containing Layer Present

The analytical results indicate that asbestos was detected above the Provincial criteria of 0.5% in all samples of the flooring collected on the ground and second floor of the Building. The additional sampling confirmed that the floor topping on lunchroom elevation of the basement level does not contain asbestos. It should be noted that the floor topping in the library in the basement (lower elevation than the lunchroom level) was previously found to contain asbestos.

Based on the findings of this sampling investigation and the previous designated substance survey report the floor topping located in Lunch Room 17, Lunch Room 18, Fan Room, Gym Storage and Storage (all rooms on the same elevation) located in the basement does not contain asbestos. However, all of the other floor toppings in the building including that located on the main floor, second floor as well as in the Library (No.16), Kitchen (010) and Storage Room (002) should be treated as asbestos containing. In addition, the floor below the existing gym floor should be inspected prior to disturbance.

Any disturbance of the asbestos floor topping is subject to O.Reg 278/05 and should only be conducted by component workers. The disposal of the asbestos containing floor topping is subject to Ontario Regulation 347: Waste Regulation.

We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.  
per:



Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A Analytical Results**

Asbestos Sampling Floor To Ceiling  
Bernard Benoit Project Management Inc.  
1000 Richmond Road Main Building  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0015-001





## PLM Summary Report

2051 Valley View Lane  
Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 15B-06479

002

Project : CFMO

Report Date : 05/27/2015

Project # : 04-0068-15-002

Sample Date : 05/25/2015

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 1

On 5/27/2015, seven (7) bulk material samples were submitted by Trent Windsor of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
LR-18/17-01A	Floor Topping, Basement Lunchrooms	None Detected - Paint None Detected - Floor Topping
LR-18/17-01B	Floor Topping, Basement Lunchrooms	None Detected - Paint None Detected - Floor Topping
LR-18/17-01C	Floor Topping, Basement Lunchrooms	None Detected - Paint None Detected - Floor Topping
005	Floor Topping	15% Chrysotile - Coating None Detected - Floor Topping
006A	Floor Topping	15% Chrysotile - Coating None Detected - Floor Topping
014	Floor Topping	15% Chrysotile - Coating None Detected - Floor Topping
012	Floor Topping	15% Chrysotile - Coating None Detected - Floor Topping

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Bruce Crabb

Lab Manager : Heather Lopez

Approved Signatory : \_\_\_\_\_

Lab Director : Bruce Crabb

Approved Signatory : \_\_\_\_\_

Thank you for choosing Moody Labs





June 10, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent, Unit B4  
Ottawa, Ontario, K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL ASBESTOS SAMPLING  
2720 RICHMOND ROAD, MAIN BUILDING  
OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Inc. (BBPM) to provide additional asbestos sampling of suspect building materials at the main building located at 2720 Richmond Road in Ottawa, Ontario (Site). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the suspect building materials prior to their disturbance at the Site.

The general contractor (Graebek Construction Ltd.) indicated that select exterior and interior walls would be demolished as part of the renovations at the site. Given the potential for asbestos to be present in the mortar they requested that the materials be sampled and analysed. In addition they discovered a potential asbestos containing paper between the 1'x1' ceiling tiles and the ceiling above.

EHS<sup>P</sup> completed the sampling on June 2, 2015. Based on the visual inspection EHS<sup>P</sup> collected and subsequently submitted twelve (12) samples from four (4) distinct potential Asbestos Containing Materials (ACMs) including interior and exterior brick mortar, concrete block mortar and paper sheeting to Steve Moody Micro Services, LLC of Farmers Branch, Texas for analysis via polarized light microscopy (PLM).

The analytical results are presented in Appendix A and are summarized in the following table:

Sample or Set ID	Description/ Location	Asbestos Concentration	Comments
CBM-01A-C	Concrete Block Mortar Interior Walls- Basement	None Detected	Not Considered ACM
INT-BM-01A-C	Brick Mortar Interior Walls- Basement	None Detected	Not Considered ACM
INT-BM-01A-C	Brick Mortar Exterior Walls- Below Windows	None Detected	Not Considered ACM
P-01A-C	Paper Sheeting Between 1'X1" Ceiling Tiles and Ceiling Above	None Detected	Not Considered ACM



---

The analytical results indicate that asbestos was not detected above the Provincial criteria of 0.5% as prescribed in Ontario Regulation 278/05 in any of the sampled materials and therefore these materials are not considered to be ACMs.

We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.  
per:

A handwritten signature in blue ink that reads "Trent Windsor". The signature is fluid and cursive, with the first name "Trent" and last name "Windsor" clearly legible.

Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A Analytical Results**

Additional Asbestos Sampling  
Bernard Benoit Project Management Inc.  
1000 Richmond Road Main Building  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0015-001





## PLM Summary Report

2051 Valley View Lane  
Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 15B-06884

Project : CFMO

Report Date : 06/09/2015

Project # : 04-0068-15-001

Sample Date : 05/07/2015

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 1

On 6/3/2015, twelve (12) bulk material samples were submitted by Trent Windsor of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
CBM-01A	Concrete Block Mortar	None Detected - Mortar
CBM-01B	Concrete Block Mortar	None Detected - Mortar
CBM-01C	Concrete Block Mortar	None Detected - Mortar
INT-BM-01A	Brick Mortar	None Detected - Brick None Detected - Mortar
INT-BM-01B	Brick Mortar	None Detected - Mortar
INT-BM-01C	Brick Mortar	None Detected - Mortar
EXT-BM-01A	Brick Mortar	None Detected - Mortar
EXT-BM-01B	Brick Mortar	None Detected - Mortar
EXT-BM-01C	Brick Mortar	None Detected - Mortar
P-01A	Paper Sheeting	None Detected - Tar Paper
P-01B	Paper Sheeting	None Detected - Tar Paper
P-01C	Paper Sheeting	None Detected - Tar Paper

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Cindy Vongpradith

Lab Manager : Heather Lopez

Approved Signatory :

Lab Director : Bruce Crabb

Approved Signatory :

Thank you for choosing Moody Labs









## PLM Summary Report

2051 Valley View Lane  
Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 15B-07725

Project : CFMO

Report Date : 06/22/2015

Project # : 04-0068-15-001

Sample Date : 06/17/2015

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 1

On 6/18/2015, nine (9) bulk material samples were submitted by Trent Windsor of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PLA-01A	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
PLA-01B	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
PLA-01C	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
TEX-PLA-01A	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Texture
TEX-PLA-01B	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Texture
TEX-PLA-01C	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Paint
FLR-01A	Flooring Material, Gym Floor	None Detected - Flooring Material None Detected - Grout
FLR-01B	Flooring Material, Gym Floor	None Detected - Flooring Material
FLR-01C	Flooring Material, Gym Floor	None Detected - Flooring Material None Detected - Grout

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Ashley Bishop

Lab Manager : Heather Lopez

Approved Signatory : \_\_\_\_\_

Lab Director : Bruce Crabb

Approved Signatory : \_\_\_\_\_

Thank you for choosing Moody Labs



**This Page Left Intentionally Blank**



Moody Labs

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

**PLM Detail Report**  
**Supplement to PLM Summary Report**

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Project : CFMO

Project # : 04-0068-15-001

Lab Job No. : 15B-07725

Report Date : 06/22/2015

Page 1 of 2

Sample Number	Layer	% Of Sample	Components	% of Layer	Analysis Date	Analyst
PLA-01A	Base Plaster (Grey)	45%	Cellulose Fibers	<1%	06/22	AB
			Aggregate	65%		
			Gypsum / Binders	35%		
	Top Plaster (White)	55%	Calcite / Gypsum Binders	100%		
PLA-01B	Base Plaster (Grey)	75%	Cellulose Fibers	<1%	06/22	AB
			Aggregate	65%		
			Gypsum / Binders	35%		
	Top Plaster (White)	25%	Calcite / Gypsum Binders	100%		
PLA-01C	Base Plaster (Grey)	70%	Cellulose Fibers	<1%	06/22	AB
			Aggregate	65%		
			Gypsum / Binders	35%		
	Top Plaster (White)	30%	Calcite / Gypsum Binders	100%		
TEX-PLA-01A	Plaster (Grey)	85%	Cellulose Fibers	<1%	06/22	AB
			Aggregate	65%		
			Gypsum / Binders	35%		
	Texture (Brown)	15%	Calcite / Gypsum Binders	100%		
TEX-PLA-01B	Plaster (Grey)	85%	Cellulose Fibers	<1%	06/22	AB
			Aggregate	65%		
			Gypsum / Binders	35%		
	Texture (Brown)	15%	Calcite / Gypsum Binders	100%		
TEX-PLA-01C	Plaster (White)	98%	Aggregate	65%	06/22	AB
			Calcite / Binders	35%		
	Paint (Off-White)	2%	Pigment / Binders	100%		
FLR-01A	Flooring Material (Orange)	97%	Cellulose Fibers	10%	06/22	AB
			Calcite / Binders	90%		
	Grout (Grey)	3%	Aggregate	65%		
			Cement Binders	35%		
FLR-01B	Flooring Material (Orange)	100%	Cellulose Fibers	10%	06/22	AB
			Calcite / Binders	90%		



Moody Labs

2051 Valley View Lane

Farmers Branch, TX 75234 Phone: (972) 241-8460

**PLM Detail Report**  
**Supplement to PLM Summary Report**

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Project : CFMO

Project # : 04-0068-15-001

Lab Job No. : 15B-07725

Report Date : 06/22/2015

Page 2 of 2

Sample Number	Layer	% Of Sample	Components	% of Layer	Analysis Date	Analyst
FLR-01C	Flooring Material (Orange)	95%	Cellulose Fibers	10%	06/22	AB
			Calcite / Binders	90%		
	Grout (Grey)	5%	Aggregate	65%		
			Cement Binders	35%		





June 24, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent, Unit B4  
Ottawa, Ontario, K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL ASBESTOS SAMPLING -  
MAIN BUILDING, GYM AND EAST STAIRWELL  
2720 RICHMOND ROAD, OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Inc. (BBPM) to provide additional asbestos sampling of suspect building materials at the main building located at 2720 Richmond Road in Ottawa, Ontario (Site). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the suspect building materials prior to their disturbance at the Site.

The general contractor (Graebek Construction Ltd.) discovered that the floor in the gymnasium was not wood parquet as initially assumed but rather a man-made composite sheeting. Based on this discovery they requested that the material be sampled and analysed for the presence of asbestos. In addition during discussions with site personnel it came to light that the East stairwell was not part of the original building. Based on this information EHS<sup>P</sup> determined that it would be prudent to sample and analyse the plaster within the stairwell for asbestos content.

EHS<sup>P</sup> completed the sampling on June 17, 2015. Based on the visual inspection EHS<sup>P</sup> collected and subsequently submitted nine (9) samples from three (3) distinct potential Asbestos Containing Materials (ACMs) including the gym flooring, and the smooth and textured plaster wall plaster in the East Stairwell. The samples were sent under chain of custody procedures to Steve Moody Micro Services, LLC of Farmers Branch, Texas for analysis via polarized light microscopy (PLM).

The analytical results are presented in Appendix A and are summarized in the following table:

Sample or Set ID	Description/ Location	Asbestos Concentration	Comments
PLA-01A-C	Smooth Plaster- East Stairwell	None Detected	Not Considered ACM
TXT-PLA-01A-C	Textured Plaster- Bottom Half of Wall in the East Stairwell	None Detected	Not Considered ACM
FLR-01A-C	Gym Flooring	None Detected	Not Considered ACM



---

The analytical results indicate that asbestos was not detected above the Provincial criteria of 0.5% as prescribed in Ontario Regulation 278/05 in any of the sampled materials and therefore these materials are not considered to be ACMs.

We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.  
per:

A handwritten signature in blue ink that reads "Trent Windsor". The signature is fluid and cursive, with the first name "Trent" and last name "Windsor" clearly legible.

Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Results**

Additional Asbestos Sampling Report  
Gym and East Stairwell  
Bernard Benoit Project Management Inc.  
Main Building, 2720 Richmond Road  
Ottawa, ON  
EHS<sup>P</sup> Project No.: 04-0068-15-001





## PLM Summary Report

2051 Valley View Lane  
Farmers Branch, TX 75234 Phone: (972) 241-8460

NVLAP Lab Code 102056-0

TDSHS License No. 30-0084

Client : EHS Partnerships Ltd. - Ottawa, ON

Lab Job No. : 15B-07725

Project : CFMO

Report Date : 06/22/2015

Project # : 04-0068-15-001

Sample Date : 06/17/2015

Identification : Asbestos, Bulk Sample Analysis

Test Method : Polarized Light Microscopy / Dispersion Staining (PLM/DS)  
EPA Method 600 / R-93 / 116

Page 1 of 1

On 6/18/2015, nine (9) bulk material samples were submitted by Trent Windsor of EHS Partnerships Ltd. - Ottawa, ON for asbestos analysis by PLM/DS. The PLM Detail Report is attached; additional information may be found therein. The results are summarized below:

Sample Number	Client Sample Description / Location	Asbestos Content
PLA-01A	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
PLA-01B	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
PLA-01C	Wall Plaster, East Stairwell	None Detected - Base Plaster None Detected - Top Plaster
TEX-PLA-01A	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Texture
TEX-PLA-01B	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Texture
TEX-PLA-01C	Textured Wall Plaster, East Stairwell	None Detected - Plaster None Detected - Paint
FLR-01A	Flooring Material, Gym Floor	None Detected - Flooring Material None Detected - Grout
FLR-01B	Flooring Material, Gym Floor	None Detected - Flooring Material
FLR-01C	Flooring Material, Gym Floor	None Detected - Flooring Material None Detected - Grout

These samples were analyzed by layers. Quantification, unless otherwise noted, is performed by calibrated visual estimate. The test report shall not be reproduced, except in full, without written approval of the laboratory. The results relate only to the items tested. These test results do not imply endorsement by NVLAP or any agency of the U.S. Government. Accredited by the National Voluntary Laboratory Accreditation Program for Bulk Asbestos Fiber Analysis under Lab Code 102056-0.



Analyst(s): Ashley Bishop

Lab Manager : Heather Lopez

Approved Signatory : \_\_\_\_\_

Lab Director : Bruce Crabb

Approved Signatory : \_\_\_\_\_

Thank you for choosing Moody Labs





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500455  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

**Attn:** Paul Park  
EHS Partnerships Ltd.  
2 Gurdwara Road  
Suite 406  
Ottawa, ON K2E 1A2

**Phone:** (613) 828-8989  
**Fax:** (613) 828-9404  
**Collected:** 7/ 7/2015  
**Received:** 7/07/2015  
**Analyzed:** 7/08/2015

**Proj:** 04-0068-15-001

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** WPL 1-a **Lab Sample ID:** 671500455-0001

**Sample Description:** Right wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015	Gray	0%	97%	3% Chrysotile	

**Client Sample ID:** WPL 1-b

**Lab Sample ID:** 671500455-0002

**Sample Description:** Stage wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-c

**Lab Sample ID:** 671500455-0003

**Sample Description:** Gym closet/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-d

**Lab Sample ID:** 671500455-0004

**Sample Description:** Left wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-e

**Lab Sample ID:** 671500455-0005

**Sample Description:** Middle closet/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)





## EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500455  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

### Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

---

**Analyst(s):** \_\_\_\_\_

Simon Parent PLM (1)

**Reviewed and approved by:**

Lemma Mohammad , Laboratory Manager  
or Other Approved Signatory

None Detected = <0.5%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON

Initial report from: 07/08/2015 12:02:23



EMSL ANALYTICAL, INC.  
LABORATORY PRODUCTS TRAINING

## Asbestos Chain of Custody

EMSL Order Number (Lab Use Only)

671500455

PHONE:  
FAX:

Company Name: EHS Partnerships Ltd.		EMSL Customer ID: 55SEA63	
Street: Suite 406, 2 Gurdwara Road		City: Ottawa	State/Province: Ontario
Zip/Postal Code: K2E 1A2	Country: Canada	Telephone #: 613-828-8989	Fax #: 613-828-9404
Report To (Name): Paul Park		Please Provide Results <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email	
Email Address: ppark@ehsp.ca		Purchase Order:	
Project Name/Number: 04-0068-15-001		EMSL Project ID (Internal Use Only):	
U.S. State Samples Taken:		CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt	
EMSL-Bill to <input type="checkbox"/> Same <input type="checkbox"/> Different - If Bill to is Different note Instructions in Comments** Third Party Billing requires written authorization from third party			
Turnaround Time (TAT) Options* - Please Check			
<input type="checkbox"/> 3 Hour <input type="checkbox"/> 6 Hour <input checked="" type="checkbox"/> 24 Hour <input type="checkbox"/> 48 Hour <input type="checkbox"/> 72 Hour <input type="checkbox"/> 96 Hour <input type="checkbox"/> 1 Week <input type="checkbox"/> 2 Week			
*For TEM Air 3 hr through 6 hr, please call ahead to schedule. There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.			
<b>PCM - Air</b> <input type="checkbox"/> Check if samples are from NY <input type="checkbox"/> NIOSH 7400 <input type="checkbox"/> w/ OSHA 8hr TWA <b>PLM - Bulk (reporting limit)</b> <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%) <input type="checkbox"/> PLM EPA NOB (<1%) Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) <input type="checkbox"/> NYS 198.1 (friable in NY) <input type="checkbox"/> NYS 198.6 NOB (non-friable-NY) <input type="checkbox"/> NYS 198.8 SOF-V <input type="checkbox"/> NIOSH 9002 (<1%)		<b>TEM - Air</b> <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763 <input type="checkbox"/> NIOSH 7402 <input type="checkbox"/> EPA Level II <input type="checkbox"/> ISO 10312 <b>TEM - Bulk</b> <input type="checkbox"/> TEM EPA NOB <input type="checkbox"/> NYS NOB 198.4 (non-friable-NY) <input type="checkbox"/> Chatfield SOP <input type="checkbox"/> TEM Mass Analysis-EPA 600 sec. 2.5 <b>TEM - Water</b> EPA 100.2 Fibers >10µm <input type="checkbox"/> Waste <input type="checkbox"/> Drinking All Fiber Sizes <input type="checkbox"/> Waste <input type="checkbox"/> Drinking	
<b>TEM - Dust</b> <input type="checkbox"/> Microvac - ASTM D 5755 <input type="checkbox"/> Wipe - ASTM D6480 <input type="checkbox"/> Carpet Sonication (EPA 600/J-93/167) <b>Soil/Rock/Vermiculite*</b> <input type="checkbox"/> PLM CARB 435 - A (0.25% sensitivity) <input type="checkbox"/> PLM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - B (0.1% sensitivity) <input type="checkbox"/> TEM CARB 435 - C (0.01% sensitivity) <input type="checkbox"/> TEM Qual via Filtration Technique <input type="checkbox"/> TEM Qual via Drop-Mount Technique *Can not accept New York State Loose Fill Vermiculite Samples <b>Other:</b> <input type="checkbox"/>			
<input checked="" type="checkbox"/> Check For Positive Stop - Clearly Identify Homogenous Group		Filter Pore Size (Air Samples) <input checked="" type="checkbox"/> 0.8µm <input type="checkbox"/> 0.45µm	
Samplers Name:		Samplers Signature:	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
WPL 1-a	wall plaster (right wall)	-	July 7 / 15 p.m.
b	(stage wall)	↓	↓
c	(gym closet)	↓	↓
d	(left wall)	↓	↓
e	(middle closet)	↓	↓
Client Sample # (s)		Total # of Samples	
Relinquished (Client) Paul Park		Date: July 7, 2015	
Received (Lab): Ottawa with SP		Time: 1:55 p.m.	
Comments/Special Instructions:		Date: 7/7/15	
		Time: 2:12 p.m.	





July 13, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent. Unit B4  
Ottawa, ON K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL ASBESTOS SAMPLING  
MAIN BUILDING, GYMNASIUM WALL PLASTER  
2720 RICHMOND ROAD, OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Incorporated (BBPM) to provide additional asbestos sampling of suspect building materials at the main building located at 2720 Richmond Road in Ottawa, Ontario (herein referred to as the 'Site'). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the suspect building materials prior to their disturbance at the Site.

The general contractor (Graebek Construction Ltd.) indicated that the gymnasium was not part of the original building, and plaster walls of select areas within the Site were found to contain asbestos. Based on this information, EHS<sup>P</sup> determined that it would be prudent to sample and analyse the plaster within the gymnasium for asbestos content.

EHS<sup>P</sup> completed the sampling on July 7, 2015. Based on the visual inspection EHS<sup>P</sup> collected and subsequently submitted five (5) samples of potential asbestos containing wall plaster in the gymnasium. The samples were sent under chain of custody procedures to EMSL Canada Incorporated of Ottawa, Ontario (EMSL) for analysis via polarized light microscopy (PLM).

The analytical results are presented in **Appendix A** and are summarized in the following table:

Sample or Set ID	Description/ Location	Asbestos Concentration	Comments
WPL 1-a to 1-e	Plaster - Gymnasium Walls	3% Chrysotile	Considered to be an ACM

The analytical results indicate that asbestos was detected above the Provincial criteria of 0.5% or more asbestos by dry weight in the samples of the wall plaster collected from within the gymnasium on the ground floor of the Building.

Based on the findings of this sampling investigation, the walls located in the gymnasium should be treated as asbestos containing.



Any disturbance of the asbestos containing wall plaster is subject to Ontario Regulation 278/05 and should only be conducted by component workers. The disposal of the asbestos containing wall plaster is subject to Ontario Regulation 347: Waste Regulation.

We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.

per:



Donghyun (Paul) Park, C.E.T., CIE, CEICI  
Environmental Technologist



Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Laboratory Results**

Additional Asbestos Sampling – Gymnasium Wall Plaster  
Bernard Benoit Project Management Inc.  
Main Building, 2720 Richmond Road  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0068-15-001





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500455  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

**Attn:** Paul Park  
EHS Partnerships Ltd.  
2 Gurdwara Road  
Suite 406  
Ottawa, ON K2E 1A2

**Phone:** (613) 828-8989  
**Fax:** (613) 828-9404  
**Collected:** 7/ 7/2015  
**Received:** 7/07/2015  
**Analyzed:** 7/08/2015

**Proj:** 04-0068-15-001

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** WPL 1-a **Lab Sample ID:** 671500455-0001

**Sample Description:** Right wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015	Gray	0%	97%	3% Chrysotile	

**Client Sample ID:** WPL 1-b

**Lab Sample ID:** 671500455-0002

**Sample Description:** Stage wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-c

**Lab Sample ID:** 671500455-0003

**Sample Description:** Gym closet/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-d

**Lab Sample ID:** 671500455-0004

**Sample Description:** Left wall/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** WPL 1-e

**Lab Sample ID:** 671500455-0005

**Sample Description:** Middle closet/Wall Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	7/08/2015					Stop Positive (Not Analyzed)





## EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500455  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

### Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

---

**Analyst(s):** \_\_\_\_\_

Simon Parent PLM (1)

**Reviewed and approved by:**

\_\_\_\_\_  
Lemma Mohammad , Laboratory Manager  
or Other Approved Signatory

None Detected = <0.5%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON

Initial report from: 07/08/2015 12:02:23





August 31, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent. Unit B4  
Ottawa, ON K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL ASBESTOS SAMPLING  
MAIN BUILDING, BASEMENT - FORMER CISTERN TAR LINING  
2720 RICHMOND ROAD, OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Incorporated (BBPM) to provide additional asbestos sampling of suspect building materials at the main building located at 2720 Richmond Road in Ottawa, Ontario (herein referred to as the 'Site'). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the suspect building materials prior to their disturbance at the Site.

The general contractor (Graebeck Construction Ltd.) indicated that tar like membrane paper was discovered within what is believed to be a former cistern in the basement.

EHS<sup>P</sup> completed the sampling on August 31, 2015. EHS<sup>P</sup> collected and subsequently submitted three (3) samples of potential asbestos containing tar paper. The samples were sent under chain of custody procedures to EMSL Canada Incorporated of Ottawa, Ontario (EMSL) for analysis via polarized light microscopy (PLM).

The analytical results are presented in *Appendix A* and are summarized in the following table:

Sample or Set ID	Description/ Location	Asbestos Concentration	Comments
TP-01 A to C	Tar paper - Cistern Lining	5% Chrysotile	Considered to be an ACM

The analytical results indicate that asbestos was detected above the Provincial criteria of 0.5% or more asbestos by dry weight in the samples of the tar paper collected from within the former cistern in basement.

Based on the findings of this sampling investigation, the tar paper lining the walls located in the basement room should be treated as asbestos containing. Any disturbance of the asbestos containing tar paper is subject to Ontario Regulation 278/05 and should only be conducted by component workers. The disposal of the asbestos containing tar paper is subject to Ontario Regulation 347: Waste Regulation.



We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.  
per:

A handwritten signature in blue ink that reads "Tim Ambery". The signature is written in a cursive, flowing style.

Tim Ambery, EIT  
Technician

A handwritten signature in blue ink that reads "Trent Windsor". The signature is written in a cursive, flowing style.

Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Laboratory Results**

Additional Asbestos Sampling – Basement –Tar Lining  
Bernard Benoit Project Management Inc.  
Main Building, 2720 Richmond Road  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0068-15-001





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500578  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

**Attn:** Tim Ambery  
EHS Partnerships Ltd.  
2 Gurdwara Road  
Suite 406  
Ottawa, ON K2E 1A2

**Phone:** (613) 828-8989  
**Fax:** (613) 828-9404  
**Collected:** 8/31/2015  
**Received:** 8/31/2015  
**Analyzed:** 8/31/2015

**Proj:** 04-0068-15-001

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** TP-01A **Lab Sample ID:** 671500578-0001

**Sample Description:** Basement room/Tar paper

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/31/2015	Gray/Black	0%	95%	5% Chrysotile	

**Client Sample ID:** TP-01B **Lab Sample ID:** 671500578-0002

**Sample Description:** Basement room/Tar paper

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/31/2015					Stop Positive (Not Analyzed)

**Client Sample ID:** TP-01C **Lab Sample ID:** 671500578-0003

**Sample Description:** Basement room/Tar paper

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	8/31/2015					Stop Positive (Not Analyzed)

### Analyst(s):

Simon Parent PLM (1)

### Reviewed and approved by:

Lemma Mohammad, Laboratory Manager  
or Other Approved Signatory

None Detected = <0.5%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON

Initial report from: 08/31/2015 15:23:11





September 9, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Inc.  
2212 Gladwin Crescent. Unit B4  
Ottawa, ON K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

**SENT VIA E-MAIL**

**RE: ADDITIONAL ASBESTOS SAMPLING  
MAIN BUILDING, EXTERIOR WALL – WATERPROOF MEMBRANE  
2720 RICHMOND ROAD, OTTAWA, ONTARIO**

Dear Mr. Leroux,

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Incorporated (BBPM) to provide additional asbestos sampling of suspect building materials at the main building located at 2720 Richmond Road in Ottawa, Ontario (herein referred to as the 'Site'). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the suspect building materials prior to their disturbance at the Site.

The general contractor (Graebek Construction Ltd.) indicated that a black waterproof membrane was discovered after excavation beside two exterior walls; the elevator exterior wall and window well exterior wall.

EHS<sup>P</sup> completed the sampling on September 3, 2015. EHS<sup>P</sup> collected and subsequently submitted six (6) samples from two (2) distinct potential Asbestos Containing Materials (ACMs) of waterproof membrane. The samples were sent under chain of custody procedures to EMSL Canada Incorporated of Ottawa, Ontario (EMSL) for analysis via polarized light microscopy (PLM).

The analytical results are presented in *Appendix A* and are summarized in the following table:

Sample or Set ID	Description/Location	Asbestos Concentration	Comments
WPM-01 A to C	Waterproof membrane – Elevator wall	None detected	Not Considered ACM
WPM-02 A to C	Waterproof membrane – Window well wall	None detected	Not Considered ACM

The analytical results indicate that asbestos was not detected above the Provincial criteria of 0.5% as prescribed in Ontario Regulation 278/05 in either of the samples of waterproof membrane collected from the exterior wall and therefore these materials are not considered to be ACMs.



We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.  
per:



Tim Ambery, EIT  
Technician



Trent Windsor, C.E.T.  
Associate



---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Laboratory Results**

Additional Asbestos Sampling – Exterior Wall – Waterproof Membrane  
Bernard Benoit Project Management Inc.  
Main Building, 2720 Richmond Road  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0068-15-001





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500597  
Customer ID: 55SEAC63  
Customer PO:  
Project ID:

**Attn:** Tim Ambery  
EHS Partnerships Ltd.  
2 Gurdwara Road  
Suite 406  
Ottawa, ON K2E 1A2

**Phone:** (613) 828-8989  
**Fax:** (613) 828-9404  
**Collected:** 9/ 3/2015  
**Received:** 9/03/2015  
**Analyzed:** 9/03/2015

**Proj:** 04-0068-15-001

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

**Client Sample ID:** WPM-01A **Lab Sample ID:** 671500597-0001

**Sample Description:** Elevator wall/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	4%	96%	None Detected	

**Client Sample ID:** WPM-01B **Lab Sample ID:** 671500597-0002

**Sample Description:** Elevator wall/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	5%	95%	None Detected	

**Client Sample ID:** WPM-01C **Lab Sample ID:** 671500597-0003

**Sample Description:** Elevator wall/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	5%	95%	None Detected	

**Client Sample ID:** WPM-02A **Lab Sample ID:** 671500597-0004

**Sample Description:** Window well/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	10%	90%	None Detected	

**Client Sample ID:** WPM-02B **Lab Sample ID:** 671500597-0005

**Sample Description:** Window well/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	10%	90%	None Detected	

**Client Sample ID:** WPM-02C **Lab Sample ID:** 671500597-0006

**Sample Description:** Window well/Waterproof membrane

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	9/03/2015	Black	15%	85%	None Detected	





October 13, 2015

EHS<sup>P</sup> Project No.: 04-0068-15-001

Mr. Andre Leroux  
Bernard Benoit Project Management Incorporated  
2212 Gladwin Crescent, Unit B4  
Ottawa, Ontario K1B 5N1  
E-mail: [Andre.Leroux@bbpm.ca](mailto:Andre.Leroux@bbpm.ca)

SENT VIA E-MAIL

**RE: ADDITIONAL ASBESTOS SAMPLING  
MAIN BUILDING, EXTERIOR  
WINDOW CAULKING AND GLAZING  
2720 RICHMOND ROAD, OTTAWA, ONTARIO**

Dear Mr. Leroux;

EHS Partnerships Limited (EHS<sup>P</sup>) was retained by Bernard Benoit Project Management Incorporated (BBPM) to provide additional asbestos sampling of suspect asbestos containing caulking and window glazing at the main building located at 2720 Richmond Road in Ottawa, Ontario (herein referred to as the 'Site'). EHS<sup>P</sup> understands that the project specific sampling was requested to satisfy Ontario Regulation 278/05 "Regulation Respecting Asbestos on Construction Projects and in Building and Repair Operations" (Ontario Regulation 278/05) to determine the asbestos content of the window caulking and glazing prior to the removal and replacement of the windows at the Site.

The general contractor (Graebek Construction Ltd.) indicated that the windows at the Site are to be replaced as part the current renovation project. Given the age of the building it is possible that the window caulking and glazing contain asbestos. It was further reported that information pertaining to the asbestos content of the window caulking and glazing was not available.

EHS<sup>P</sup> completed the sampling program on October 9, 2015. EHS<sup>P</sup> collected and subsequently submitted a total of six (6) samples of potential asbestos containing building materials including window caulking and glazing. The samples were sent under chain of custody procedures to EMSL Canada Incorporated of Ottawa, Ontario (EMSL) for analysis via polarized light microscopy (PLM).

The analytical results are presented in **Appendix A** and are summarized in the following table:

Sample or Set ID	Description/Location	Asbestos Concentration	Comments
EWC 1-A to C	Exterior Window Caulking – Around window frame	None detected	Not Considered ACM
WG 1-A to C	Window Glazing – Around window glass	15% Chrysotile	Considered to be an ACM

The analytical results indicate that asbestos was not detected in the samples of the window caulking; however, asbestos was detected above the Provincial criteria of 0.5% or more asbestos by dry weight in the samples of the window glazing collected from the window within the Site. Based on the findings of this sampling investigation, all window glazing at the Site should be treated as asbestos containing.



Any disturbance of the asbestos containing window glazing is subject to Ontario Regulation 278/05 and should only be conducted by component workers. The removal of the glazing would be considered to be a Type 1 asbestos abatement operation as long as power tools are not utilized.

The disposal of the asbestos containing window glazing is subject to Ontario Regulation 347: Waste Regulation.

We trust that the above meets your requirements at this time. If you have any questions, please feel free to contact us at (613) 828-8989.

Sincerely,

EHS PARTNERSHIPS LTD.

per:



Donghyun (Paul) Park, C.E.T., CIE, CEICI  
Environmental Technologist





---

## LIMITATIONS

The conclusions and recommendations contained in this assessment report are based upon professional opinions with regard to the subject matter. These opinions are in accordance with currently accepted environmental assessment standards and practices applicable to these locations and are subject to the following inherent limitations:

1. The data and findings presented in this report are valid as of the dates of the investigations. The passage of time, manifestation of latent conditions or occurrence of future events may warrant further exploration at the properties, analysis of the data, and re-evaluation of the findings, observations, and conclusions expressed in this report.
2. The data reported and the findings, observations and conclusions expressed in this report are limited by the Scope of Work. The Scope of Work was defined by the request of the client, the time and budgetary constraints imposed by the client, and availability of access to the properties.
3. Because of the limitations stated above, the findings, observations and conclusions expressed by EHS<sup>P</sup> in this report are not, and should not be, considered an opinion concerning compliance of any past or present owner or operator of the site with any federal, provincial or local laws or regulations.
4. No warranty or guarantee, whether expressed or implied, is made with respect to the data or the reported findings, observations, and conclusions, which are based solely upon site conditions in existence at the time of investigation.
5. EHS<sup>P</sup> assessment reports present professional opinions and findings of a scientific and technical nature. While attempts were made to relate the data and findings to applicable environmental laws and regulations, the report shall not be construed to offer legal opinion or representations as to the requirements of, nor compliance with, environmental laws, rules, regulations or policies of federal, provincial, or local governmental agencies. Any use of the assessment report constitutes acceptance of the limits of EHS<sup>P</sup>'s liability. EHS<sup>P</sup>'s liability extends only to its client and not to other parties who may obtain this assessment report. Issues raised by the report should be reviewed by appropriate legal counsel.



## **Appendix A**

### **Analytical Laboratory Results**

Additional Asbestos Sampling  
Window Caulking and Glazing  
Bernard Benoit Project Management Inc.  
Main Building, 2720 Richmond Road  
Ottawa, Ontario  
EHS<sup>P</sup> Project No.: 04-0068-15-001





# EMSL Canada Inc.

22 Antares Drive Suite 102 Ottawa, ON K2E 7Z6  
 Phone/Fax: 343-882-6076 / (343) 882-6077  
<http://www.EMSL.com> / [ottawalab@EMSL.com](mailto:ottawalab@EMSL.com)

EMSL Canada Order 671500721  
 Customer ID: 55SEAC63  
 Customer PO:  
 Project ID:

**Attn:** Paul Park  
 EHS Partnerships Ltd.  
 2 Gurdwara Road  
 Suite 406  
 Ottawa, ON K2E 1A2

**Phone:** (613) 828-8989  
**Fax:** (613) 828-9404  
**Collected:** 10/ 9/2015  
**Received:** 10/09/2015  
**Analyzed:** 10/09/2015

**Proj:** 04-0068-15-001

## Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

<b>Client Sample ID:</b> EWC 1-a			<b>Lab Sample ID:</b> 671500721-0001			
<b>Sample Description:</b> Exterior window caulking						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> EWC 1-b			<b>Lab Sample ID:</b> 671500721-0002			
<b>Sample Description:</b> Exterior window caulking						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> EWC 1-c			<b>Lab Sample ID:</b> 671500721-0003			
<b>Sample Description:</b> Exterior window caulking						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015	Gray	0%	100%	None Detected	
<b>Client Sample ID:</b> WG 1-a			<b>Lab Sample ID:</b> 671500721-000z			
<b>Sample Description:</b> Window glazing						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015	Gray	0%	85%	15% Chrysotile	
<b>Client Sample ID:</b> WG 1-b			<b>Lab Sample ID:</b> 671500721-0005			
<b>Sample Description:</b> Window glazing						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015				Stop Positive (Not Analyzed)	
<b>Client Sample ID:</b> WG 1-c			<b>Lab Sample ID:</b> 671500721-0006			
<b>Sample Description:</b> Window glazing						
TEST	Analyzed date	Color	Don-Asbestos		Asbestos	CoF F ent
			Nibrous	Don-Nibrous		
PLM	10/09/2015				Stop Positive (Not Analyzed)	





[golder.com](http://golder.com)