

# SUPPLEMENTAL INSTRUCTION



CONTRACTOR:  
Tal-co Building Innovations Ltd.  
Suite A, 4728 Bank Street  
Ottawa, ON K1T 3W7

PROJ.: Meridian Community  
Building Rebuild  
PROJ. No.: 1841  
DATE: June 26, 2019  
S.I. No. S.I. – A002

Supplemental Instructions are issued only for the purpose of recording any clarification or interpretation of the contract documents or giving direction on problems resulting from field conditions. These instructions are subject to the provisions of the contract documents and unless stated herein and specifically co-authorized by the Client, will not affect the contract. Should the Contractor require a change in the contract price or project schedule, he shall submit to the Architect within ten (10) days of the date hereof, an itemized proposal. If the proposal is accepted by the Client, this Supplemental Instruction will be superseded by a Change order.

**2.1 TITLE**  
Existing Column In Stair

**2.2 REFERENCE**  
Contractor's Information Request No. 04

**2.3 DESCRIPTION OF THE WORK**  
.1 The existing steel column in the north-west corner of the stair can be cut at the ground floor level and the wall above framed with load-bearing 2x6 wood studs as noted in the response to CRI#04 by Goodeve Structural Inc.

**2.4 ATTACHMENTS**  
Goodeve Structural Inc. Response to CRI#04

**2.5 REASON**  
Site conditions.

## Partners

Barry J. Hobin  
OAA, FRAIC, Hon. Fellow AIA

William A. Davis  
OAA, MRAIC, Associate AIA

Gordon Lorimer  
OAA, FRAIC, Associate AIA

Wendy Brawley  
OAA, MRAIC, Associate AIA

Douglas Brooks  
Senior Arch. Tech.

## Directors

Marc Thivierge  
OAA, MRAIC

Reinhard Vogel  
Senior Arch. Tech.

## Associates

Bryan Bonell  
OAA, MRAIC, Associate AIA

William Ritcey  
MRAIC

Dan Henhoeffler  
Senior Arch. Tech.

## Hobin Architecture Incorporated

63 Pamilla Street  
Ottawa, Ontario  
Canada K1S 3K7

t 613-238-7200  
f 613-235-2005

[hobinarc.com](http://hobinarc.com)

Distribution:

Owner       City Authority       Electrical       Struct.       Landscaping  
 Contractor       File       Mech.       Civil       Other

June 21, 2019

Hobin Architecture Incorporated  
63 Pamilla Street  
Ottawa, ON  
K1S 3K7

Attn: Mr. Bryan Bonell

Dear Sir,

**Re: Meridian Community Building Re-Build  
CIR NO.: 04 – Structural Review**

Further to Talco's structural queries of 18 June 2019, CIR No: 04, we have the following comments:

**Structural Items**

**Talco Comment #1**

Reference Item #2.2.1 - Provide Structural Site Instruction with respect to the reviewed slab leaks at the new canopy area down to the Garage (Near parking spots #34).

***Goodeve Structural Inc. Response #1***

As reviewed and discussed with Talco on site no structural remediation required.  
Roofing to be repaired.

.../2

June 21, 2019

**Re: Meridian Community Building Re-Build  
CIR NO.: 04**

**Structural Items (cont'd)**

**Talco Comment #2**

Reference Item #2.2.2 - Provide Site Instruction to confirm that the existing steel column can be cut at the floor level. TBIL's proposal is to frame 2x6 bearing walls above to provide better lateral strength to framing. This change will result in no cost change.

***Goodeve Structural Inc. Response #2***

As discussed on site with Talco, column may be cut at floor level as requested by Talco.

Please contact our office if you have any questions.

Yours truly,



Peter Goodeve, P. Eng.  
GOODEVE STRUCTURAL INC.

PG: cam

E-mailed

[bbonell@hobinarc.com](mailto:bbonell@hobinarc.com)