

SUPPLEMENTAL INSTRUCTION



CONTRACTOR:
Tal-co Building Innovations Ltd.
Suite A, 4728 Bank Street
Ottawa, ON K1T 3W7

PROJ.: Meridian Community
Building Rebuild
PROJ. No.: 1841
DATE: Oct. 8, 2019
S.I. No. S.I. – A012

Supplemental Instructions are issued only for the purpose of recording any clarification or interpretation of the contract documents or giving direction on problems resulting from field conditions. These instructions are subject to the provisions of the contract documents and unless stated herein and specifically co-authorized by the Client, will not affect the contract. Should the Contractor require a change in the contract price or project schedule, he shall submit to the Architect within ten (10) days of the date hereof, an itemized proposal. If the proposal is accepted by the Client, this Supplemental Instruction will be superseded by a Change order.

12.1 TITLE

Delete Light Fixture in Storage Room 113

12.2 REFERENCE

CIR #29 Light Fixture Type 3 in Storage Room 113

12.3 DESCRIPTION OF THE WORK

.1 Delete one light fixture in Storage Room 113 as per the response to CIR #29 by Goodkey, Weedmark & Associates. Centre remaining light in the room. Turn deleted light fixture over to owner.

12.4 ATTACHMENTS

Goodkey Weedmark & Associates response to CIR #29 Light Fixture Type 3 in Storage Room 113

12.5 REASON

Coordination.

Partners

Barry J. Hobin
OAA, FRAIC, Hon. Fellow AIA

William A. Davis
OAA, MRAIC, Associate AIA

Gordon Lorimer
OAA, FRAIC, Associate AIA

Wendy Brawley
OAA, MRAIC, Associate AIA

Douglas Brooks
Senior Arch. Tech.

Directors

Marc Thivierge
OAA, MRAIC

Reinhard Vogel
Senior Arch. Tech.

Associates

Bryan Bonell
OAA, MRAIC, Associate AIA

William Ritcey
MRAIC

Dan Henhoeffler
Senior Arch. Tech.

Hobin Architecture Incorporated

63 Pamilla Street
Ottawa, Ontario
Canada K1S 3K7

t 613-238-7200
f 613-235-2005

hobinarc.com

Distribution:

Owner City Authority Electrical Struct. Landscaping
 Contractor File Mech. Civil Other



Project: Meridian Community Building Re-build
1-3 Meridian Place
Ottawa ON, K26 6N1

CONTRACTOR'S INFORMATION REQUEST FORM

DATE: October 3, 2019 **CIR NO.:** 29

TO: Bryan; Mark, Yves; Judi;
Allan; Robert; Scott.
DISCIPLINE: Electrical Request
 Mechanical Request
 Structural Request
Architectural Request
 Landscape Request
 Specification Request
 Other

FROM: TAL-CO BUILDING INNOVATIONS LIMITED
 (General Contractor)

<u>Annie Griffiths</u> (Project Administrator)	SPECIFICATION	<u>N/A</u>
	SECTION:	<u>N/A</u>
<u>613-821-2938</u> (Office Fax Number)	DWG NO.:	<u>N/A</u>
	DETAIL NO.:	<u>N/A</u>

INFORMATION REQUESTED:

1. Please confirm new location for Light Fixture Type 3 in Storage Room #113 due to Attic Access Hatch interference. Access Hatch size is 550mm x 900mm. Location of access hatch is highlighted in orange on the attached photo. Edge of Attic Access Hatch is approximately 40" from wall.

(Requested by): **Tal-Co /**


REPLY:

One Type 3 light fixture to be deleted to accommodate roof access hatch.

Marc Trottier

Goodkey, Weedmark & Associates Limited

2019-10-04



End of CIR #29